ılıılı cısco

End-of-Sale and End-of-Life Announcement for the Cisco ME 3600X Series Ethernet Access Switches and 3800X Series Carrier Ethernet Switch Routers, Cisco IOS Release 15.3(1)S

EOL9039

Cisco announces the end-of-sale and end-of-life dates for the Cisco ME 3600X Series Ethernet Access Switches and 3800X Series Carrier Ethernet Switch Routers, Cisco IOS Release 15.3(1)S. The last day to order the affected product(s) is July 17, 2013. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	January 16, 2013
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 17, 2013
Last Ship Date: OS SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 17, 2013
End of SW Maintenance Releases Date: OS SW	The last date that Cisco Engineering may release any final software maintenance January 15, 2014 releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	
Last Date of Support:	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 31, 2018

Table 1. End-of-Life Milestones and Dates for the Cisco ME 3600X Series Ethernet Access Switches and 3800X Series Carrier Ethernet Switch Routers, Cisco IOS Release 15.3(1)S

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
S360XTVK9T-15301S	Cisco ME 360X 24CX SERIES IOS UNIVERSAL TAR
S360XTVK9T-15301S=	Cisco ME 360X 24CX SERIES IOS UNIVERSAL TAR
S360XTVT-15301S	Cisco ME 360X 24CX SERIES IOS UNIVERSAL W/O CRYPTO TAR
S360XTVT-15301S=	Cisco ME 360X 24CX SERIES IOS UNIVERSAL W/O CRYPTO TAR
S360XVK9T-15301S	Cisco ME 360X SERIES IOS UNIVERSAL TAR

End-of-Sale Product Part Number	Product Description	
S360XVT-15301S	Cisco ME 360X SERIES IOS UNIVERSAL W/O CRYPTO TAR	
S380XVK9T-15301S	Cisco ME 380X SERIES IOS UNIVERSAL TAR	
S380XVT-15301S	Cisco ME 380X SERIES IOS UNIVERSAL W/O CRYPTO TAR	

Product Migration Options

There is no replacement available for the Cisco ME 3600X Series Ethernet Access Switches and 3800X Series Carrier Ethernet Switch Routers, Cisco IOS Release 15.3(1)S at this time.

Customers are encouraged to migrate to the Cisco ME 3600X Series Ethernet Access Switches and 3800X Series Carrier Ethernet Switch Routers, Cisco IOS Release 15.3(2)S. Information about this product can be found at: http://www.cisco.com/en/US/products/ps10965/index.html.

Service prices for Cisco products are subject to change after the product End-of-Sale date

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco ME3600X and ME 3800X Series, Cisco IOS Release 15.3(2)S, visit <u>http://www.cisco.com/en/US/products/ps10965/index.html</u>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: <u>http://www.cisco.com/en/US/products/products end-of-life policy.html</u>.

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: <u>http://www.cisco.com/web/feeds/products/end_of_life_rss.xml</u>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA