

Product Bulletin No. 3261

# **Cisco Catalyst Blade Switch 3030 for Dell**

Cisco Systems<sup>®</sup> announces the new Cisco<sup>®</sup> Catalyst<sup>®</sup> Blade Switch 3030 for Dell. The Cisco Catalyst Blade Switch 3030 is an integrated switch for the Dell PowerEdge Blade Server that extends Cisco intelligent network services to the server edge and uses existing network investments to help reduce operational expenses.

Designed for the Dell Power Edge Blade Server Enclosure, the Cisco Catalyst Blade Switch 3030 helps ensure consistency across the network for advanced services such as security and resiliency. It also allows customers to take advantage of the end-to-end Cisco management framework to simplify ongoing operations.

# **ORDERING INFORMATION**

Table 1 provides lists the part numbers and product descriptions for the Cisco Catalyst Blade Switch 3030 for Dell.

Part Number	Description
WS-CBS3030-DEL-S WS-CBS3030-DEL-F	<ul> <li>Cisco Catalyst Blade Switch 3030 for Dell—spare</li> <li>Cisco Catalyst Blade Switch 3030 for Dell—factory-installed into Blade Server Enclosure from Dell</li> </ul>
GLC-SX-MM=	• Gigabit Ethernet (GE) small form-factor pluggable (SFP), LC connector, short-wavelength (SX) transceiver
GLC-T=	GE SFP, RJ-45 connector 1000BASE-T

Table 1. Ordering Information for Cisco Catalyst Blade Switch 3030 for Dell

The Cisco Catalyst Blade Switch 3030 provides the following hardware configuration:

- 10 internal 1000BASE-T ports connected to servers through the PowerEdge Enclosure backplane
- 4 external 10/100/1000 SFP-based ports; the switch supports copper and fiber SX SFP modules from Cisco
- 2 external 10/100/1000BASE-T ports
- 1 external console port

Available with Cisco IOS<sup>®</sup> Software, LAN Base image, the Cisco Catalyst Blade Switch 3030 offers a complete set of intelligent services to deliver security, quality of service (QoS), and high availability in the server farm access environment.

# PRODUCT AVAILABILITY

The new Cisco Catalyst Blade Switch 3030 for Dell begins shipping March 2006.

# FOR MORE INFORMATION

For more information about the Cisco Catalyst Blade Switch 3030, visit <u>http://www.cisco.com/go/cbs3030</u> or contact your local account representative.

## SERVICE AND SUPPORT

Cisco SmartNet<sup>®</sup> maintenance contracts are available for the Cisco Catalyst Blade Switch 3030 for Dell.



### **Corporate Headquarters**

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 526-4100 European Headquarters Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

#### **Americas Headquarters**

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883

# Asia Pacific Headquarters

Cisco Systems, Inc. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com Tel: +65 6317 7777 Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at www.cisco.com/go/offices**.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

© 2006 Cisco Systems, Inc. All rights reserved. Important notices, privacy statements, and trademarks of Cisco Systems, Inc. can be found on cisco.com. Page 3 of 3