

## End-of-Sale and End-of-Life Announcement for the Laser Link Platform

EOL7625

Cisco announces the end-of-sale and end-of-life dates for the Laser Link Platform. The last day to order the affected product(s) is November 30, 2011. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions, even if this date exceeds the Last Date of Support shown in Table 1.

Milestone	Definition	Date	
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	June 1, 2011	
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 30, 2011	
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	February 28, 2012	
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	November 29, 2012	
End of New Service Attachment Date: HW	achment Date: the last date to order a new service-and-support contract or add the equipment and/or		
End of Service Contract Renewal Date: HW	February 25, 2016		
Last Date of Support: HW	The last expected date to receive service and support for the product as entitled by applicable service contracts or warranty terms and conditions **. After this date, all support services for the product are unavailable, and the product Accomes obsolete. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	November 30, 2016	

Table 1.	End-of-Life Milestones and Dates for the Laser Link Platform

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
252871	(LLFR-SP)Fwd Rx,SP	See the Product Migration Options section below for detailed information on replacing this product.		
252872	(LLFR-SA)Fwd Rx,SA	See the Product Migration Options section below for detailed information on replacing this product.		
252953	(LLDA)Amp,2/Out,870MHz, MainFrame Mounted	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
253257	(LLNT 1550.92 CH33)LL1550nm DM Tx,870MHz,CH33,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253258	(LLNT 1552.52 CH31)LL1550nm DM Tx,870MHz,CH31,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253259	(LLNT 1554.13 CH29)LL1550nm DM Tx,870MHz,CH29,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253260	(LLNT 1555.75 CH27)LL1550nm DM Tx,870MHz,CH27,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253261	(LLNT 1557.36 CH25)LL1550nm DM Tx,870MHz,CH25,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253262	(LLNT 1558.98 CH23)LL1550nm DM Tx,870MHz,CH23,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253263	(LLNT 1560.61 CH21)LL1550nm DM Tx,870MHz,CH21,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253296	(LLNTR 1560.61 CH21)LL1550nm DM Rev Tx,210MHz,CH21,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253297	(LLNTR 1558.98 CH23)LL1550nm DM Rev Tx,210MHz,CH23,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253298	(LLNTR 1557.36 CH25)LL1550nm DM Rev Tx,210MHz,CH25,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253299	(LLNTR 1555.75 CH27)LL1550nm DM Rev Tx,210MHz,CH27,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253300	(LLNTR 1554.13 CH29)LL1550nm DM Rev Tx,210MHz,CH29,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253301	(LLNTR 1552.52 CH31)LL1550nm DM Rev Tx,210MHz,CH31,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253302	(LLNTR 1550.92 CH33)LL1550nm DM Rev Tx,210MHz,CH33,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253303	(LLNTR 1549.32 CH35)LL1550nm DM Rev Tx,210MHz,CH35,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253345	Opt Sw,Sgl Rack Unit,Sgl Sw Component	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
253346	Opt Sw,Sgl Rack Unit,2 Sw Components	See the Product Migration Options section below for detailed information on replacing this product.		
253347	Opt Sw,Sgl Rack Unit,3 Sw Components	See the Product Migration Options section below for detailed information on replacing this product.		
253531	(LLRS)LaserLink RF Sw	See the Product Migration Options section below for detailed information on replacing this product.		
253560	LLOS UPG Kit	See the Product Migration Options section below for detailed information on replacing this product.		
253704	(LLOA-C-14BM)Modular Opt Amp,EDFA-14,Input Isolator,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253706	(LLOA-C-17BM)Modular Opt Amp,EDFA-17,Input Isolator,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253708	(LLOA-C-20BM)Modular Opt Amp,EDFA-20,Input Isolator,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253710	(LLOA-C-22BM)Modular Opt Amp,EDFA-22,Input Isolator,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253745	(LLNTR 1547.72 CH37)LL1550nm DM Rev Tx,210MHz,CH37,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253749	(LLNTR 1546.12 CH39)LL1550nm DM Rev Tx,210MHz,CH39,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253753	(LLNTR 1544.53 CH41)LL1550nm DM Rev Tx,210MHz,CH41,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253757	(LLNTR 1542.94 CH43)LL1550nm DM Rev Tx,210MHz,CH43,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253765	(LLNTR 1539.77 CH47)LL1550nm DM Rev Tx,210MHz,CH47,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253773	(LLNTR 1536.61 CH51)LL1550nm DM Rev Tx,210MHz,CH51,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253777	(LLNTR 1535.04 CH53)LL1550nm DM Rev Tx,210MHz,CH53,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253781	(LLNTR 1533.47 CH57)LL1550nm DM Rev Tx,210MHz,CH55,SA	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
253785	(LLNTR 1531.90 CH57)LL1550nm DM Rev Tx,210MHz,CH57,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253789	(LLNTR 1530.33 CH59)LL1550nm DM Rev Tx,210MHz,CH59,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253793	(LLNT 1541.35 CH45)LL1550nm DM Tx,870MHz,CH45,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253801	(LLNT 1538.19 CH49)LL1550nm DM Tx,870MHz,CH49,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253809	(LLNT 1535.04 CH53)LL1550nm DM Tx,870MHz,CH53,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253817	(LLNT 1531.90 CH57)LL1550nm DM Tx,870MHz,CH57,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253821	(LLNT 1530.33 CH59)LL1550nm DM Tx,870MHz,CH59,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253877	(LLT 1550nm-MPN)LLT 1550Tx,870MHz,Modular,Pr em,NTSC	See the Product Migration Options section below for detailed information on replacing this product.		
253878	(LLT1550-MSN)LLT 1550Tx,870MHz,Modular,St d,NTSC	See the Product Migration Options section below for detailed information on replacing this product.		
253897	(ELLRR-SA)Enhncd Rtn Rx,AGC,5-210MHz,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253898	(ELLRR-SP)Enhncd Rtn Rx,AGC,5-210MHz,SP	See the Product Migration Options section below for detailed information on replacing this product.		
253899	(ELLRR-SC/E2)Enhncd Rtn Rx,AGC,5-210MHz,SC/E2	See the Product Migration Options section below for detailed information on replacing this product.		
253922	(LLTIII-5 APC)LLIII Tx,1GHz,Ser5,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253924	(LLTIII-7 APC)LLIII Tx,1GHz,Ser7,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253925	(LLTIII-8 APC)LLIII Tx,1GHz,Ser8,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253927	(LLTIII-10 APC)LLIII Tx,1GHz,Ser10,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
253928	(LLTIII-11 APC)LLIII Tx,1GHz,Ser11,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253929	(LLTIII-12 APC)LLIII Tx,1GHz,Ser12,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253930	(LLTIII-13 APC)LLIII Tx,1GHz,Ser13,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253931	(LLTIII-14 APC)LLIII Tx,1GHz,Ser14,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253932	(LLTIII-15 APC)LLIII Tx,1GHz,Ser15,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
253936	(LLTIII-3 UPC)LLIII Tx,1GHz,Ser3,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
253937	(LLTIII-4 UPC)LLIII Tx,1GHz,Ser4,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
253938	(LLTIII-5 UPC)LLIII Tx,1GHz,Ser5,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
253939	(LLTIII-6 UPC)LLIII Tx,1GHz,Ser6,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
253940	(LLTIII-7 UPC)LLIII Tx,1GHz,Ser7,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
253941	(LLTIII-8 UPC)LLIII Tx,1GHz,Ser8,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
253942	(LLTIII-9 UPC)LLIII Tx,1GHz,Ser9,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
253943	(LLTIII-10 UPC)LLIII Tx,1GHz,Ser10,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
253944	(LLTIII-11 UPC)LLIII Tx,1GHz,Ser11,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
253945	(LLTIII-12 UPC)LLIII Tx,1GHz,Ser12,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
253946	(LLTIII-13 UPC)LLIII Tx,1GHz,Ser13,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
253947	(LLTIII-14 UPC)LLIII Tx,1GHz,Ser14,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
254038	Mainframe,User Pnl,-20 to 65C	See the Product Migration Options section below for detailed information on replacing this product.		
254040	MainFrame,AC PS,User Pnl,-20 to 65C	See the Product Migration Options section below for detailed information on replacing this product.		
254041	MainFrame,AC PS,EMIC,- 20 to 65C	See the Product Migration Options section below for detailed information on replacing this product.		
254042	MainFrame,DC PS,EMIC,- 20 to 65C	See the Product Migration Options section below for detailed information on replacing this product.		
254043	MainFrame,DC PS,User Pnl,-20 to 65C	See the Product Migration Options section below for detailed information on replacing this product.		
254046	PS,LLIII Mainframe,Red,AC In,-20 to 65C	See the Product Migration Options section below for detailed information on replacing this product.		
254047	PS,LLIII Mainframe,Red,DC In,-20 to 65C	See the Product Migration Options section below for detailed information on replacing this product.		
254057	EMIC for LLIII Mainframe	See the Product Migration Options section below for detailed information on replacing this product.		
254178	(LLT1550-MPP)LLT 1550Tx,870MHz,Modular,Pr em,PAL	See the Product Migration Options section below for detailed information on replacing this product.		
254179	(LLT1550-MSP)LLT 1550Tx,870MHz,Modular,St d,PAL	See the Product Migration Options section below for detailed information on replacing this product.		
254347	(LLT1550-MSN)LLT 1550Tx,870MHz,Modular,St d,NTSC40H	See the Product Migration Options section below for detailed information on replacing this product.		
254348	(LLT1550-MSN)LLT 1550Tx,870MHz,Modular,St d,NTSC40L	See the Product Migration Options section below for detailed information on replacing this product.		
254696	(LLNT 1542.94 CH43)LL1550nm DM Tx,870MHz,CH43,SA	See the Product Migration Options section below for detailed information on replacing this product.		
254697	(LLNT 1544.53 CH41)LL1550nm DM Tx,870MHz,CH41,SA	See the Product Migration Options section below for detailed information on replacing this product.		
704095	Ears,Mounting,23in,5RU,LLI II	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
714110001	LLIII Fan Cover Assembly	See the Product Migration Options section below for detailed information on replacing this product.		
R253256	(LLNT 1550.92 CH33)LL1550nm DM Tx,870MHz,CH35,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R253348	Opt Sw,Sgl Rack Unit,4 Sw Components	See the Product Migration Options section below for detailed information on replacing this product.		
R253761	(LLNT 1550.92 CH33)LL1550nm DM Rev Tx,870MHz,CH45,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R253769	(LLNT 1550.92 CH33)LL1550nm DM Rev Tx,870MHz,CH49,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R253797	(LLNT 1550.92 CH33)LL1550nm DM Tx,870MHz,CH47,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R253805	(LLNT 1550.92 CH33)LL1550nm DM Tx,870MHz,CH51,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R253813	(LLNT 1550.92 CH33)LL1550nm DM Tx,870MHz,CH55,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R253920	(LLTIII-3 APC)LLIII Tx,1GHz,Ser3,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R253921	(LLTIII-4 APC)LLIII Tx,1GHz,Ser4,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R253923	(LLTIII-6 APC)LLIII Tx,1GHz,Ser6,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R253926	(LLTIII-9 APC)LLIII Tx,1GHz,Ser9,Half- Width,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R253948	(LLTIII-15 UPC)LLIII Tx,1GHz,Ser15,Half- Width,SP	See the Product Migration Options section below for detailed information on replacing this product.		
R254698	(LLNT 1550.92 CH33)LL1550nm DM Tx,870MHz,CH39,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R254699	(LLNT 1550.92 CH33)LL1550nm DM Tx,870MHz,CH37,SA	See the Product Migration Options section below for detailed information on replacing this product.		
R494950002	Cable,LLII,9 Pin to 15 Pin (LLDA)	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
R708660001	Cable,LLII,15 Pin to 15 Pin,Blue	See the Product Migration Options section below for detailed information on replacing this product.		
R708660002	Cable,LLIII,26 Pin to 26 Pin (1550 ExMod,EDFA),White	See the Product Migration Options section below for detailed information on replacing this product.		
R708660004	Cable,LLII,26 Pin to 15 Pin (1550 ExMod,EDFA),Green	See the Product Migration Options section below for detailed information on replacing this product.		
R710830001	Cable,LLIII,26 Pin to 26 Pin (LLIII 1310 Tx),Brown	See the Product Migration Options section below for detailed information on replacing this product.		
R710830002	Cable,LLIII,26 Pin to 15 Pin (LLIII 1310 Tx),Black	See the Product Migration Options section below for detailed information on replacing this product.		

## **Product Migration Options**

Customers are encouraged to migrate to the Prisma II or Prisma XD platform. Information about this product can be found at: <u>http://www.cisco.com/en/US/products/ps8863/index.html</u>.

Customers can use the Cisco Technology Migration Program (TMP) to trade-in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at <a href="http://www.cisco.com/web/partners/pr11/incentive/tmp/index.html">http://www.cisco.com/web/partners/pr11/incentive/tmp/index.html</a>.

Customers may be able to continue to purchase the Laser Link Platform through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <u>http://www.cisco.com/go/eos</u>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about\_cisco\_takeback\_recycling.html.

## For More Information

For more information about the Prisma II or Prisma XD Optical Transmission Platform, visit <u>http://www.cisco.com/en/US/products/ps8863/index.html</u>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: <u>http://www.cisco.com/en/US/products/products end-of-life policy.html</u>.

\*\* For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod warranties listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html.

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end\_of\_life\_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)

Printed in USA