



## End-of-Sale and End-of-Life Announcement for the Cisco DPA 7600 Series Voice Mail Gateways

Cisco Systems® announces the end-of-sale and end-of life dates for the Cisco DPA 7600 Series Voice Mail Gateways. The last day to order the affected product is May 16, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 in EoL product bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco DPA 7600 Series Voice Mail Gateways. Table 2 lists the product part numbers affected by this announcement.

All models in the series are affected by this notice, which includes the Cisco DPA 7610 and 7630 Voice Mail Gateways.

**Table 1.** End-of-Life Milestones and Dates for the Cisco DPA 7600 Series Voice Mail Gateways.

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 15, 2006
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 16, 2007
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 14, 2007
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	May 15, 2008
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 15, 2008
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	August 11, 2011
<b>Last Date of Support: HW</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 14, 2012

HW = Hardware

OS SW = Operating System Software

App SW = Application Software


**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
<b>DPA-7610</b>	DPA 7610 Voice Mail Gateway. 24 Ports, 2 wire Nortel/Octel
<b>DPA-7610=</b>	Spare for DPA 7610 Voice Mail Gateway. 24 Ports, 2 wire Nortel/Octel
<b>DPA-7630</b>	DPA 7630 Voice Mail Gateway. 24 ports, 4 wire Avaya/Octel
<b>DPA-7630=</b>	Spare for DPA 7630 Voice Mail Gateway. 24 ports, 4 wire Avaya/Octel

### PRODUCT MIGRATION OPTIONS

There is no replacement available for the Cisco DPA 7600 Series Voice Mail Gateways at this time.

The Cisco DPA 7610 and DPA 7630 Voice Mail Gateways enable legacy voicemail equipment, specifically the Octel 200 and 300 (Serenade) and the Octel 250 and 350 (Aria) working with the Nortel Meridian 1 PBX and the Avaya Definity PBX, to connect to a Cisco Unified Communications system network. The manufacturer of these products announced their end of sale on June 30, 2005. Thus, Cisco can no longer offer support for this solution. Cisco Unified CallManager customers with Avaya/Octel or Nortel/Octel traditional voicemail systems are encouraged to migrate to Cisco Unity Voice Messaging. The Cisco Unity system supports several networking options to traditional voice messaging systems, including Audio Messaging Interchange Specification (AMIS), Voice Protocol for Internet Mail (VPIM) and the Cisco Unity Bridge for even tighter integration with Avaya/Octel voicemail systems. Alternatively, customers can support



their traditional voicemail system through Simple Messaging Desktop Interface (SMDI) integration via a direct connection to a Cisco Unified CallManager server or using the Cisco VG248 Analog Voice Gateway.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

[http://www.cisco.com/en/US/ordering/or6/or17/order\\_refurbished\\_equipment\\_high\\_level\\_listing.html](http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_high_level_listing.html).

## **FOR MORE INFORMATION**

For more information about the Cisco DPA 7600 Series Voice Mail Gateways, visit <http://www.cisco.com/en/US/products/hw/gatecont/ps821/ps822/index.html> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



**Corporate Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www.europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**  
Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco.com Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic  
Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy  
Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal  
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

Printed in USA

C51-367061-00 09/06