

End-of-Sale and End-of-Life Announcement for the Select Cisco 2000 Series Wireless LAN Controller

EOL5117—Amended

Cisco[®] announces the end-of-sale and end-of life dates for the Select Cisco 2000 Series Wireless LAN Controller. The last day to order the affected product(s) is April 2, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

This announcement affects the Cisco 2000 Series Wireless LAN Controller with part number AIR-WLC2006-K9 only. Customers are encouraged to migrate to the replacement Cisco 2106 Wireless LAN Controller with part number AIR-WLC2106-K9.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	February 9, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 2, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 22, 2007
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	July 22, 2008
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	April 22, 2008
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	July 20, 2011
Last Date of Support: HW	••• •• •• •• •• •• •• •• •• •• •• •• ••	

 Table 1.
 End-of-Life Milestones and Dates for the Select Cisco 2000 Series Wireless LAN Controller

HW = Hardware OS SW = Operating System Software App. SW = Application Software

 Table 2.
 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
AIR-LAP1510BUN0501	Cisco 1500 Mesh Starter Kit, 5 AP Bundle, FCC	There is currently no replacement product available for this product.	
AIR-PWR-2006-AC=	Spare Power Supply for WLC2006	AIR-PWR-2106-AC=	WLC2106 power supply
AIR-WLC2006-K9	2000 Series WLAN Controller for up to 6 Lightweight APs	AIR-WLC2106-K9	2100 Series WLAN Controller for up to 6 Lightweight APs

Product Migration Options

Customers are encouraged to migrate to the new Cisco Wireless LAN Controller with part number AIR-WLC2106-K9, which provides the same software functionality and offers better hardware with an expanded number of ports, including two Power over Ethernet (PoE) ports.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: http://www.cisco.com/go/tradein/. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Certified Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to: http://cisco.com/go/remarketing

For More Information

For more information about the Cisco 2106 Wireless LAN Controller (with part number AIR-WLC2106-K9), visit <u>http://www.cisco.com/en/US/products/ps6366/index.html</u>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod end of life.html

To subscribe to receive end-of-life/end-of-sale information, go to:

http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice



Americas Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000 800 553-NETS (6387)

Fax: 408 527-0883

Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com Tel: +65 6317 7777 Fax: +65 6317 7779

Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands

www-europe.cisco.com Tel: +31 0 800 020 0791 Fax: +31 0 20 357 1100

Europe Headquarters

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCVP, the Cisco logo, and Welcome to the Human Network are trademarks of Cisco Systems, Inc.: Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems, Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTinet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc.; and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (071 R)

Printed in USA

C51-388361-01 11/07