



New and Changed Information

This topic provides the new and changed feature information for the Cisco ONS 15454 DWDM Troubleshooting Guide.

- [New and Changed Information, page i](#)

New and Changed Information

Table 1: New and Changed Features

Feature	Description	Release	Where Documented
CP-UNVER-CLEARED	Control Plane Unverified Cleared Alarm	9.6.0.3	<i>Alarm Troubleshooting</i> chapter: • CP-UNVER-CLEARED Alarm
PWR-CON-LMT	Power Consumption Limit Alarm	9.6.0.3	<i>Alarm Troubleshooting</i> chapter • PWR-CON-LMT • Clear the PWR-CON-LMT Alarm
FIPS_TEST_FAILED	FIPS Test Failed Alarm	9.8	<i>Alarm Troubleshooting</i> chapter • FIPS_TEST_FAILED • Clearing the FIPS_TEST_FAILED Alarm
KEY_EX_FAIL	Key Exchange Fail Alarm	9.8	<i>Alarm Troubleshooting</i> chapter • KEY_EX_FAIL • Clearing the KEY_EX_FAIL Alarm

Feature	Description	Release	Where Documented
KEY_WRITE_FAIL	Key Write Fail Alarm	9.8	<i>Alarm Troubleshooting</i> chapter • KEY_WRITE_FAIL • Clearing the KEY_WRITE_FAIL Alarm
OVER-TEMP-UNIT-PROT	Over Temperature Unit Protection Alarm	9.8	<i>Alarm Troubleshooting</i> chapter • OVER-TEMP-UNIT-PROT • Clearing the OVER-TEMP-UNIT-PROT Alarm
SEQ_MISMATCH_COUNT	Sequence Mismatch Count Alarm	9.8	<i>Alarm Troubleshooting</i> chapter • SEQ_MISMATCH_COUNT • Clearing the SEQ_MISMATCH_COUNT Alarm
UNIT-HIGH-TEMP	Unit High Temperature Alarm	9.8	<i>Alarm Troubleshooting</i> chapter • UNIT-HIGH-TEMP • Clearing the UNIT-HIGH-TEMP Alarm