



Cisco ASR 1000 Series Aggregation Services Routers Documentation Roadmap

This document roadmap describes the Cisco ASR 1000 Series Aggregation Services Router documentation and provides links to access the documentation online.

Technical Documentation Ideas Forum

Suggest ways Cisco technical documentation can be improved and better serve your needs. Participate in the Technical Documentation Ideas forum at:

<http://www.cisco.com/go/techdocideas>

Contents

Use this index as an online directory to quickly access publications for your product. This index includes the following sections:

- [Cisco Open Source Licensing Information, page 2](#)
- [Important Information About Cisco IOS XE Releases, page 2](#)
- [Hardware Documentation, page 2](#)
- [Software Documentation, page 3](#)
- [Shared Port Adapter Documentation, page 3](#)
- [Maintain and Operate Documentation, page 3](#)
- [Obtaining Documentation and Submitting a Service Request, page 5](#)
- [Cisco IOS XE Documentation, page 4](#)
- [Cisco IOS XE Documentation, page 4](#)
- [Obtaining Documentation and Submitting a Service Request, page 5](#)



Americas Headquarters:
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2011 Cisco Systems, Inc. All rights reserved.

Cisco Open Source Licensing Information

Cisco IOS-XE software, Copyright (c) 2005-2011 by Cisco Systems, Inc.

Certain components of Cisco IOS-XE software are licensed under the GNU General Public License (GPL) Version 2.0. The software code licensed under GPL Version 2.0 is free software that comes with ABSOLUTELY NO WARRANTY. You can redistribute and (or) modify such GPL code under the terms of GPL Version 2.0.

For detailed information, go to: [Open Source Licensing Information for Cisco ASR 1000 IOS XE 3](#)

Important Information About Cisco IOS XE Releases

Starting from November, 2011, the Cisco IOS XE Release 3.4.0S is upgraded to Cisco IOS XE Release 3.5.0S. The Cisco IOS XE Release 3.5.0S has enhanced hardware that includes support for clear-channel E3 ATM on the SPA-2CHT3-CE-ATM on Cisco ASR 1000 Series Router.

Starting from July, 2011, the Cisco IOS XE Release 3.3.0S is upgraded to Cisco IOS XE Release 3.4.0S. The Cisco IOS XE Release 3.4.0S has introduced new hardware which are two new SPAs: 24-Port Channelized T1/E1 ATM CEoP SPA (Circuit Emulation Mode only) and 2-Port Channelized T3/E3 ATM CEoP SPA (ATM Mode only) on Cisco ASR 1000 Series Router.

Starting in March, 2011, the Cisco IOS XE Release 3.2.0S is upgraded to Cisco IOS XE Release 3.3.0S. The Cisco IOS XE Release 3.3.0S has introduced new hardware which are new SPAs: 1-Port 10-Gigabit Ethernet LAN/WAN Phy SPA and 1-Port Channelized OC-3 STM1 ATM CEoP SPA (Circuit Emulation Mode only) on Cisco ASR 1000 Series Router.

Starting in July, 2010, Cisco IOS XE software is moving from the current Cisco IOS XE Release 2.6 to Cisco IOS XE Release 3.1S to introduce new hardware (ASR1000-ESP40, ASR1000-SIP40, Cisco ASR 1013 Router) and an enhanced Cisco IOS 15.0(1) S software that runs on improved componentized code for Cisco IOS features.

The Cisco IOS XE release numbering scheme is modified by the addition of the suffix 'S' to the release number to denote the release branch that will differentiate the different products using Cisco IOS XE release.

As pointed out, the underlying Cisco IOS software numbering scheme for the Cisco ASR 1000 Series Routers changes from the current numbering of 12.2(33)XNx to 15.0(1)S. This change will define simpler numbering for new feature releases (the number in parenthesis) and rebuilds. The 15.x(x)Sx releases will continue to be time-based and time-synchronized with Cisco IOS XE releases.

Hardware Documentation

Step-by-step instructions for installing or upgrading a Cisco ASR Series Aggregation Services Router. To open a document, click the link provided.

- [Cisco ASR 1000 Series Hardware Installation Guide](#)
- [Cisco ASR 1006 Router Quick Start Guide](#)
- [Cisco ASR 1004 Router Quick Start Guide](#)
- [Cisco ASR 1002 Router Quick Start Guide](#)
- [Cisco ASR 1002-F Router Quick Start Guide](#)
- [Cisco ASR 1013 Router Quick Start Guide](#)

- [Cisco ASR 1001 Router Quick Start Guide](#)

Software Documentation

Detailed, step-by-step instructions for configuring a Cisco ASR Series Aggregation Services Router, including configuration examples, network diagrams, and technical concepts. To open a document, click the link provided:

- [Cisco ASR 1000 Series Aggregation Services Routers Software Configuration Guide](#)
- [Cisco IOS XE System Messages](#)
- [Cisco Unified Border Element \(SP Edition\) Command Reference: Distributed Model](#)
- [Cisco Unified Border Element \(SP Edition\) Configuration Guide: Distributed Model](#)
- [Cisco Unified Border Element \(SP Edition\) Command Reference: Unified Model](#)
- [Cisco Unified Border Element \(SP Edition\) Configuration Guide: Unified Model](#)
- [Cisco Unified Border Element \(SP Edition\) Configuration Profile Examples](#)

Shared Port Adapter Documentation

Detailed, step-by-step instructions for installing and configuring a shared port adapter on a Cisco ASR Series Aggregation Services Router. To open a document, click the link provided:

- [Cisco ASR 1000 Series Aggregation Services Routers SIP and SPA Hardware Installation Guide](#)
- [Cisco ASR 1000 Series Aggregation Services Routers SIP and SPA Software Configuration Guide](#)

Maintain and Operate Documentation

Maintain and operate guides describe the tasks required to maintain, administer, and use a Cisco ASR 1000 Aggregation Services Router. To open a document, click the link provided:

- [Cisco ASR 1000 Series Aggregation Services Routers Operations and Maintenance Guide](#)
- [Cisco ASR 1000 Series Routers ROMmon Upgrade Guide](#)
- [Upgrading to the Cisco ASR 1000 Series Routers ROMmon Image Release 12.2\(33r\)XNB](#)
- [Upgrading to the Cisco ASR 1000 Series Routers ROMmon Image Release 12.2\(33r\)XN2](#)
- [Upgrading to the Cisco ASR 1000 Series Routers ROMmon Image Release 12.2\(33r\)XNC0](#)
- [Upgrading to the Cisco ASR 1000 Series Routers ROMmon Image Release 12.2\(33r\)XND](#)
- [Upgrading Field Programmable Hardware Devices for Cisco ASR 1000 Series Routers](#)

Other Documentation

To open a document, click the link provided:

- [Cisco ASR 1000 Series Aggregation Services Routers MIB Specifications Guide](#)
- [Network Address Translation \(NAT\) and Firewall Application Layer Gateway \(ALG\) Support on Cisco ASR 1000 Series Routers](#)
- [Cisco ASR 1000 Embedded Services Processor 10G Non-Crypto Capable Feature](#)

Regulatory Compliance and Safety Information

Click the link to open the [Regulatory Compliance and Safety Information for the Cisco ASR 1000 Series Aggregation Services Routers](#)

Cisco IOS XE Documentation

To open a document, click the link provided:

- Click the link to open the:
 - [Release Notes for Cisco ASR 1000 Series Aggregation Services Routers for Cisco IOS XE Release 3S](#)
 - [Release Notes for Cisco ASR 1000 Series Aggregation Services Routers for Cisco IOS XE Release 2](#)
- Click the link to see a list of:
 - [Cisco IOS XE 3S Software Configuration Guides](#)
 - [Cisco IOS XE, Release 2 Software Configuration Guides](#)

Troubleshooting Tool

To open a document, click the link provided:

- [Return Material Authorization \(RMA\) Instructions](#)
- [RMA FAQs](#)
- [Support Tools and Resources](#)

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly What's New in Cisco Product Documentation, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

Subscribe to the What's New in Cisco Product Documentation as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a freeservice and Cisco currently supports RSS version 2.0.

CCDE, CCENT, CCSI, Cisco Eos, Cisco Explorer, Cisco HealthPresence, Cisco IronPort, the Cisco logo, Cisco Nurse Connect, Cisco Pulse, Cisco SensorBase, Cisco StackPower, Cisco StadiumVision, Cisco TelePresence, Cisco TrustSec, Cisco Unified Computing System, Cisco WebEx, DCE, Flip Channels, Flip for Good, Flip Mino, Flipshare (Design), Flip Ultra, Flip Video, Flip Video (Design), Instant Broadband, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn, Cisco Capital, Cisco Capital (Design), Cisco:Financed (Stylized), Cisco Store, Flip Gift Card, and One Million Acts of Green are service marks; and Access Registrar, Aironet, AllTouch, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Lumin, Cisco Nexus, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, Continuum, EtherFast, EtherSwitch, Event Center, Explorer, Follow Me Browsing, GainMaker, iLNX, IOS, iPhone, IronPort, the IronPort logo, Laser Link, LightStream, Linksys, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, PCNow, PIX, PowerKEY, PowerPanels, PowerTV, PowerTV (Design), PowerVu, Prisma, ProConnect, ROSA, SenderBase, SMARTnet, Spectrum Expert, StackWise, WebEx, and the WebEx logo are registered trademarks of Cisco and/or its affiliates in the United States and certain other countries.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

