

## **Release Notes for RV220W Firmware Version** 1.0.0.26

January 2011

These Release Notes describe the known issues in RV220W firmware version 1.0.0.26.

## Contents

This document includes the following topics:

- Known Issues In RV220W Firmware Version 1.0.0.26
- Related Information

## Known Issues In RV220W Firmware Version 1.0.0.26

The following are known issues in firmware version 1.0.0.26:

 If the cable connecting the router to the network is disconnected, the router loses its IP address. When you reconnect the router to the network, it does not recover its IP address.

To resolve this issue, restart the router by pressing the power button off and then back on. After startup, the router recovers its IP address.

- Proxy server access blocking under Firewall does not work properly.
- SNMP MIBs only support Read access.
- SSL VPN using Firefox browser can result in loss of VPN connectivity. Use Internet Explorer as a workaround.
- To configure SSL VPN on the router from a Mac computer, you must enable the root account on the computer and use the account to establish an SSL VPN tunnel to the RV220W router. For more information about enabling the root user, see Mac Help on your system or visit Apple's Support website.
- WLAN clients fail to connect to the router using WPA Enterprise or WPA2 Enterprise.

To work around this issue, disable the Block Fragmentation option in the Firewall page.

An issue with enabling the Aggressive mode for IPSec VPN.

Use the Main mode instead as a workaround.

- An issue with Daylight Savings Time.
- Some Atheros wireless clients cannot connect to RV220W when wireless security is enabled.
- An issue with the DHCP Relay mode if the DHCP server is on the WAN.

## **Related Information**

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/go/sbsc
Cisco Small Business Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Small Business Products. No login is required. Downloads for all other Cisco Small Business products, including Network Storage Systems, are available in the Download area on Cisco.com at www.cisco.com/go/software (registration/login required).
Product Documentation	
Cisco RV220W	http://www.cisco.com/en/US/products/ps9923/ tsd_products_support_series_home.html
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb

Cisco, Cisco Systems, the Cisco logo, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries. All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0705R)

© 2011 Cisco Systems, Inc. All rights reserved.

OL-24250-01