



# Release Notes for Hot Patch 1 for AsyncOS 8.0 for Email

---

Published: September 3, 2013

## Contents

- [Upgrade Paths, page 1](#)
- [Resolved Issues, page 1](#)
- [Additional Information, page 2](#)
- [Service and Support, page 2](#)

## Upgrade Paths

You can upgrade to release 8.0.0-701 from the following versions:

- 8.0.0-671

## Resolved Issues

Click a Defect ID in the table for more information about the defect.

**Table 1**      **Resolved Issues in This Release**

Defect ID	Description
<a href="#">CSCuh94813</a>	Stellent timeout failure can DOS the workqueue.



---

**Americas Headquarters:**  
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

## Additional Information

For additional information about AsyncOS for Cisco Email Security Appliances, see the Release Notes for your release at [http://www.cisco.com/en/US/products/ps10154/prod\\_release\\_notes\\_list.html](http://www.cisco.com/en/US/products/ps10154/prod_release_notes_list.html).

## Service and Support

For service and support information for Cisco Content Security appliances, see:

- [http://www.cisco.com/en/US/support/tsd\\_cisco\\_worldwide\\_contacts.html](http://www.cisco.com/en/US/support/tsd_cisco_worldwide_contacts.html)
- [http://www.cisco.com/en/US/products/ps11169/serv\\_group\\_home.html#~Support](http://www.cisco.com/en/US/products/ps11169/serv_group_home.html#~Support)

If you purchased support through a reseller or another supplier, please contact that supplier directly with your product support issues.

For noncritical questions and issues, you can also submit a customer support request from the appliance. For instructions, see the User Guide or online help.

---

This document is to be used in conjunction with the documents listed in the “Additional Information” section.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2013 Cisco Systems, Inc. All rights reserved.