

Release Notes for SGE2010/2010P

November, 2009

These Release Notes describe the recommended practices and known issues that apply to the SGE2010/2010P for the following software versions:

Firmware	
Firmware Version	3.0.0.18
Firmware Image Name	SGE20x0x_FW_3.0.0.18.ros
Firmware Release Date	November, 2009
Bootcode	
Boot Code Version	2.0.0.03
Boot Code Image Name	cisco_bp_sge_boot-20003.rfb
Boot Code Release Date	June, 2009

Contents

- [“New and Changed Information,” on page 2](#)
- [“Limitations and Restrictions,” on page 2](#)
- [“Where to Find Support,” on page 2](#)

New and Changed Information

Firmware versions 3.0.0.18

- Corrects the condition where the SFP ports in a stack do not automatically come back up after the backup master becomes the master, or the original master rejoins the stack.

Limitations and Restrictions

- Devices running phase 1 (1.0.x.y) firmware must be upgraded to firmware version 3.0.0.17 using the EasyUpgrade first before upgrading to firmware version 3.0.0.18 using the regular upgrade procedure. Refer to the release notes for firmware 3.0.0.17 and the EasyUpgrade documentation for details.

Where to Find Support

To obtain current support information for Cisco Small Business products, visit the following URLs:

www.cisco.com/en/US/products/ps9967/tsd_products_support_series_home.html

www.cisco.com/go/smallbizsupport

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, Cisco WebEx, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0809R)

© 2009 Cisco Systems, Inc. All rights reserved.