

Release Notes for Cisco Small Business SPA8800 Analog Telephone Adapter Firmware Version 6.1.1 1(XU)

July 2013

These Release Notes describe the new features and enhancements in the Cisco Small Business SPA8800 Analog Telephone Adapter firmware version 6.1.1 1(XU).

Contents

This document includes the following topics:

- [Changes in Firmware Version 6.1.1 1\(XU\)](#)
- [Installation Notes](#)
- [Related Information](#)

Changes in Firmware Version 6.1.1 1(XU)

SRTP functionality has been removed, and it cannot be configured or provisioned in firmware versions designated with an "XU" in the filename.

Installation Notes

To install firmware for the Cisco Small Business SPA8800 Analog Telephone Adapter with Router, follow these instructions.

Downloading Firmware

Always download and install the latest firmware for your ATA device before doing any configurations. For the latest firmware go to the URL given below,

http://www.cisco.com/en/US/products/ps10024/tsd_products_support_series_home.html

and click the **Download Software** link.

Upgrading the Firmware for the ATA Device

In this procedure, install the firmware files which have been downloaded previously.

STEP 1 Determine the address of the ATA device:

- a. Connect an analog telephone to the Phone 1 or Phone 2 port on the ATA device. (You may not hear a dial tone. Continue to step b.)
- b. Press **** on the keypad to access the IVR menu.
- c. Press 110# to determine the Internet (WAN) IP address.

STEP 2 Make a note of the IP address that is announced.

NOTE If the administration computer is connected to the Ethernet port of the ATA device, the default IP address is 192.168.0.1.

STEP 3 Use the administration computer to install the latest firmware:

- a. Extract the Zip file, and then run the executable file to upgrade the firmware.
- b. When the Firmware Upgrade Warning window appears, click Continue.
- c. In the next window that appears, enter the IP address of the ATA device, and then click OK.
- d. In the Confirm Upgrade window, verify that the correct device information and product number appear. Then click Upgrade.
- e. A progress message appears while the upgrade is in progress. The success window appears when the upgrade is completed. The device reboots.
- f. Click OK to close the confirmation message.

- g. To verify the upgrade, point the web browser to the IP address of the ATA device. Check the Router > Status page. The Software Version field should show the firmware version that you installed.

NOTE You may need to refresh your browser to display the updated page reflecting the new version number.

Related Information

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp
Cisco Small Business Firmware Downloads	www.cisco.com/go/smallbizfirmware
Product Documentation	
Cisco SPA8000	www.cisco.com/go/smallbizvoicegateways
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2013 Cisco Systems, Inc. All rights reserved.

78-21338-01