

**PRODUCT BULLETIN 2718** 

# END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR CISCO CATALYST 6500 SERIES NETWORK ANALYSIS MODULE SOFTWARE 3.1 AND SOFTWARE LICENSE OPTIONS FOR FIRST-GENERATION NAM

Cisco Systems<sup>®</sup> announces the end-of-sale and end-of-life dates for Cisco<sup>®</sup> Catalyst<sup>®</sup> 6500 Series Network Analysis Module (NAM) Software 3.1 for the first-generation NAM. This includes the end-of-sale of software license options for both application response time (ART) and voice-over-IP (VoIP) monitoring. These licenses are enabled through Cisco Catalyst 6500 Series NAM Software 3.1 on the first-generation NAM. The last day to order the software and licenses is June 15, 2005. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until June 15, 2008.

Table 1 describes the end-of-life milestones, definitions, and dates for Cisco Catalyst 6500 Series NAM Software 3.1 for the first-generation NAM. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the second-generation NAM with Cisco NAM Software 3.3 or later to take advantage of new features, increased performance, and monitoring enhancements. Second-generation NAMs are available in two hardware versions, NAM-1 and NAM-2, to meet diverse network analysis needs in a switching environment running up to gigabit speeds.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	December 29, 2004
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 15, 2005
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 15, 2005
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	June 15, 2006
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	June 15, 2006

 Table 1.
 End-of-Life Milestones and Dates for Cisco Catalyst 6500 Series NAM Software 3.1 for the First-Generation NAM

Milestone	Definition	Date
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	December 15, 2007
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	June 15, 2008

## Table 2. Product Part Numbers Affected By This Announcement

End-of-Sale Product Part Number	Product Description	
SC-SVC-NAM-3.1	Cisco Catalyst 6500 Series NAM Software 3.1 for the first-generation NAM (WS-X6380-NAM)	
SC6K-NAM-ART-LIC	Right-to-use license for ART monitoring option for use only with the Cisco Catalyst 6500 Series first-generation NAM (WS-X6380-NAM)	
SC6K-NAM-VOIP-LIC	Right-to-use license for VoIP monitoring option for use only with the Cisco Catalyst 6500 Series first-generation NAM (WS-X6380-NAM)	

## **PRODUCT MIGRATION OPTIONS**

The recommended replacement for Cisco Catalyst 6500 Series NAM Software 3.1 for the first-generation NAM is the Cisco NAM-1 or NAM-2 with NAM software 3.3.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <u>http://www.cisco.com/go/tradein/</u>. The Cisco TMP application requires all users to have a Cisco.com user ID.

### FOR MORE INFORMATION

For more information about the Cisco NAM-1 or NAM-2, contact your local account representative or visit: http://www.cisco.com/go/nam/

For more information about the Cisco End-of-Life Policy, visit: http://www.cisco.com/en/US/products/prod\_end\_of\_life.html

To subscribe to receive Cisco end-of-life/end-of-sale information, visit: <u>http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice</u>



Corporate Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 526-4100 European Headquarters Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

Americas Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883

#### Asia Pacific Headquarters Cisco Systems, Inc. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com Tel: +65 6317 7777 Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices.

Argentina • Australia • Australia • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco Powered Network mark, Cisco Unity, Follow Me Browsing, FormShare, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherShitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MGX, MICA, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, ScriptShare, SideCast, SMARTnet, StrataView Plus, Stratm, SwitchProbe, TeleRouter, The Fastest Way to Increase Your Internet Quotient, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0402R) 204105.61\_ETMG\_LF\_12.04

© 2004 Cisco Systems, Inc. All rights reserved. Important notices, privacy statements, and trademarks of Cisco Systems, Inc. can be found on cisco.com. Page 4 of 4