

End-of-Sale and End-of-Life Announcement for the Cisco Wireless LAN Controller Module (WLCM)

EOL7941

Cisco announces the end-of-sale and end-of-life dates for the Cisco Wireless LAN Controller Module (WLCM). The last day to order the affected product(s) is April 23, 2012. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco Wireless LAN Controller Module (WLCM)

| Milestone | Definition | Date |
|---|---|------------------|
| End-of-Life Announcement Date | The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public. | October 24, 2011 |
| End-of-Sale Date | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | April 23, 2012 |
| Last Ship Date: OS SW, HW | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | July 22, 2012 |
| End of SW Maintenance Releases Date: OS SW, HW | The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software. | April 23, 2013 |
| End of Routine Failure Analysis Date: HW | The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect. | April 23, 2013 |
| End of New Service Attachment Date: OS SW, HW | For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract. | April 23, 2013 |
| End of Service Contract Renewal Date: OS SW, HW | The last date to extend or renew a service contract for the product. | July 19, 2016 |
| Last Date of Support: HW | The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. | April 30, 2017 |

HW = Hardware OS SW = Operating System Software App. SW = Application Software

 Table 2.
 Product Part Numbers Affected by This Announcement

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|------------------------------------|---|---------------------------------|--|------------------------|
| NME-AIR-WLC12-K9 | 12-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25 | 25 AP Base License for WLCM2 on SRE | - |
| NME-AIR-WLC12-K9 | 12-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25A | 25 AP Adder Licenses for WLC on SRE | |
| NME-AIR-WLC12-K9 | 12-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-700-K9 | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC12-K9 | 12-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-900-K9 | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC12-K9= | 12-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25 | 25 AP Base License for WLCM2 on SRE | - |
| NME-AIR-WLC12-K9= | 12-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25A | 25 AP Adder Licenses for WLC on SRE | - |
| NME-AIR-WLC12-K9= | 12-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-5 | 5 AP License for WLCM2 on SRE | - |
| NME-AIR-WLC12-K9= | 12-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-5A | 5 AP Adder Licenses for WLC on SRE | - |
| NME-AIR-WLC12-K9= | 12-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-700-K9= | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC12-K9= | 12-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-900-K9= | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC25-K9 | 25-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25 | 25 AP Base License for WLCM2 on SRE | - |
| NME-AIR-WLC25-K9 | 25-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25A | 25 AP Adder Licenses for WLC on SRE | - |
| NME-AIR-WLC25-K9 | 25-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-700-K9 | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC25-K9 | 25-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-900-K9 | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC25-K9= | 25-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25 | 25 AP Base License for WLCM2 on SRE | - |
| NME-AIR-WLC25-K9= | 25-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25A | 25 AP Adder Licenses for WLC on SRE | - |
| NME-AIR-WLC25-K9= | 25-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-700-K9= | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC25-K9= | 25-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-900-K9= | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC6-K9 | 6-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25 | 25 AP Base License for WLCM2 on SRE | - |
| NME-AIR-WLC6-K9 | 6-AP WLAN Controller NM | FL-SRE-WLC-25A | 25 AP Adder Licenses for | - |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---------------------------------|---|---------------------------------|---|------------------------|
| | for Cisco 2800/3800 Series | | WLC on SRE | |
| NME-AIR-WLC6-K9 | 6-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-700-K9 | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC6-K9 | 6-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-900-K9 | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC6-K9= | 6-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25 | 25 AP Base License for WLCM2 on SRE | - |
| NME-AIR-WLC6-K9= | 6-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25A | 25 AP Adder Licenses for WLC on SRE | - |
| NME-AIR-WLC6-K9= | 6-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-5 | 5 AP License for WLCM2 on SRE | - |
| NME-AIR-WLC6-K9= | 6-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-5A | 5 AP Adder Licenses for WLC on SRE | - |
| NME-AIR-WLC6-K9= | 6-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-700-K9= | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC6-K9= | 6-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-900-K9= | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC8-K9 | 8-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25 | 25 AP Base License for WLCM2 on SRE | - |
| NME-AIR-WLC8-K9 | 8-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25A | 25 AP Adder Licenses for WLC on SRE | - |
| NME-AIR-WLC8-K9 | 8-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-700-K9 | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC8-K9 | 8-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-900-K9 | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC8-K9= | 8-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25 | 25 AP Base License for WLCM2 on SRE | - |
| NME-AIR-WLC8-K9= | 8-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-25A | 25 AP Adder Licenses for WLC on SRE | - |
| NME-AIR-WLC8-K9= | 8-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-5 | 5 AP License for WLCM2 on SRE | - |
| NME-AIR-WLC8-K9= | 8-AP WLAN Controller NM for Cisco 2800/3800 Series | FL-SRE-WLC-5A | 5 AP Adder Licenses for WLC on SRE | - |
| NME-AIR-WLC8-K9= | 8-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-700-K9= | Services Module with Services Ready Engine (SRE) | - |
| NME-AIR-WLC8-K9= | 8-AP WLAN Controller NM for Cisco 2800/3800 Series | SM-SRE-900-K9= | Services Module with Services Ready Engine (SRE) | - |
| SWLCEK9-52 | WLAN Controller SW for ISR NMEWLC - ED | SW-SRE-WLC-7.0-K9 | Cisco Wireless LAN Controller Module Software Release 7.0 | - |
| SWLCEK9-60 | Cisco Unified WLAN Controller SW Release 6.0 - MD | SW-SRE-WLC-7.0-K9 | Cisco Wireless LAN Controller Module Software Release 7.0 | - |

Product Migration Options

Customers are encouraged to migrate to the Cisco 2900/3900 Series Services-Ready Engine Modules. Information about this product can be found at: http://www.cisco.com/en/US/products/hw/wireless/index.html.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Wireless LAN Controller Module (WLCM) through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: http://www.cisco.com/qo/eos.

Service prices for Cisco products are subject to change after the product End-of-Sale date

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco Services-Ready Engine Modules, visit http://www.cisco.com/en/US/products/hw/wireless/index.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

http://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

 $Cisco\ has\ more\ than\ 200\ offices\ worldwide.\ Addresses,\ phone\ numbers,\ and\ fax\ numbers\ are\ listed\ on\ the\ Cisco\ Website\ at\ www.cisco.com/go/offices.$

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-691054-00 10/11