

End-of-Sale and End-of-Life Announcement for the Cisco MDS 9000 Family 4 Gbps Fibre Channel Longwave SFP Transceiver (4-km Reach)

EOL7376

Cisco announces the end-of-sale and end-of life dates for the Cisco MDS 9000 Family 4 Gbps Fibre Channel Longwave SFP Transceiver (4-km Reach). The last day to order the affected product(s) is August 1, 2011. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco MDS 9000 Family 4 Gbps Fibre Channel Longwave SFP Transceiver (4-km Reach)

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	January 31, 2011
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	August 1, 2011
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 30, 2011
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	July 31, 2012
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 31, 2012
End of Service Contract Renewal Date: HW		
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
DS-SFP-FC4G-MR	4 Gbps Fibre Channel-LW SFP, LC, (4km Reach)	DS-SFP-FC4G-LW	4 Gbps Fibre Channel-LW SFP, LC, (10km Reach)	
DS-SFP-FC4G-MR	4 Gbps Fibre Channel-LW SFP, LC, (4km Reach)	DS-SFP-FC8G-LW	8 Gbps Fibre Channel LW SFP+, LC	
DS-SFP-FC4G-MR=	4 Gbps Fibre Channel, LW SFP, LC, (4km Reach), spare	DS-SFP-FC4G-LW=	4 Gbps Fibre Channel-LW SFP, LC, (10km Reach) spare	
DS-SFP-FC4G-MR=	4 Gbps Fibre Channel, LW SFP, LC, (4km Reach), spare	DS-SFP-FC8G-LW=	8 Gbps Fibre Channel LW SFP+, LC	

Product Migration Options

Customers are encouraged to migrate to Cisco MDS 9000 Family 4- or 8-Gbps Fibre Channel Longwave SFP or SFP+ Transceivers (10-km Reach). Information about these products can be found at:

http://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps4358/product_data_sheet09186a00801bc698.html

Customers may purchase the Cisco MDS 9000 Family 4- and 8-Gbps Fibre Channel Longwave SFP or SFP+ Transceivers (10-km Reach) from EMC Corporation, IBM Corporation, Hitachi Data Systems, Hewlett-Packard, Xiotech, Sun, Network Appliance, Dell, NEC, or Fujitsu, all of whom are designated original storage manufacturer (OSM) or solution technology integrator (STI) partners, or from any of these companies' resellers. Cisco does not offer trade-in credits or a trade-in program for Cisco MDS 9000 family products.

For More Information

For more information about the Cisco MDS 9000 Family 4- or 8-Gbps Fibre Channel Longwave SFP or SFP+ Transceiver (10-km Reach), visit

http://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps4358/product_data_sheet09186a00801bc698.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html

To subscribe to receive end-of-life/end-of-sale information, go to:

http://www.cisco.com/cisco/support/notifications.html

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)

Printed in USA C51-642853-01 02/11