

## End-of-Sale and End-of-Life Announcement for the Cisco Mobile Wireless Transport Manager 6.0

EOL6619

Cisco® announces the end-of-sale and end-of life dates for the Cisco Mobile Wireless Transport Manager 6.0. The last day to order the affected product(s) is August 24, 2009. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Cisco Mobile Wireless Transport Manager 6.0

| Milestone                                                | Definition                                                                                                                                                                                                                            | Date              |
|----------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| <b>End-of-Life Announcement Date</b>                     | The date the document that announces the end of sale and end of life of a product is distributed to the general public.                                                                                                               | February 23, 2009 |
| <b>End-of-Sale Date</b>                                  | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.                                                                                                         | August 24, 2009   |
| <b>Last Ship Date:<br/>App. SW</b>                       | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.                                                                                             | November 22, 2009 |
| <b>End of SW Maintenance Releases Date:<br/>App. SW</b>  | The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.                     | August 24, 2010   |
| <b>End of New Service Attachment Date:<br/>App. SW</b>   | For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract. | August 24, 2010   |
| <b>End of Service Contract Renewal Date:<br/>App. SW</b> | The last date to extend or renew a service contract for the product.                                                                                                                                                                  | November 20, 2011 |
| <b>Last Date of Support:<br/>App. SW</b>                 | The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.                                                                | August 23, 2012   |

HW = Hardware      OS SW = Operating System Software      App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

| End-of-Sale Product Part Number | Product Description                                         | Replacement Product Part Number | Replacement Product Description                             |
|---------------------------------|-------------------------------------------------------------|---------------------------------|-------------------------------------------------------------|
| <b>MWTM-6.0-5.0UP-K9</b>        | Mobile Wireless Transport Mgr 6.0 - Migration from MWTM 5.x | MWTM-6.X-5.0UP-K9               | Mobile Wireless Transport Mgr 6.0 - Migration from MWTM 5.x |
| <b>MWTM-6.0-BASE-K9</b>         | Mobile Wireless Transport Mgr 6.0 Base Media Kit            | MWTM-6.X-BASE-K9                | Mobile Wireless Transport Mgr 6.X Base Media Kit            |
| <b>MWTM-6.0-SGM3UP-K9</b>       | Mobile Wireless Transport Mgr 6.0 - Migration from SGM 3.x  | MWTM-6.X-SGM3UP-K9              | Mobile Wireless Transport Mgr 6.X - Migration from SGM 3.x  |
| <b>MWTM-6.0-SGM4UP-K9</b>       | Mobile Wireless Transport Mgr 6.0 - Migration from SGM 4.x  | MWTM-6.X-SGM4UP-K9              | Mobile Wireless Transport Mgr 6.X - Migration from SGM 4.x  |
| <b>MWTM-6.0IT-2K-RTU</b>        | Mobile Wireless Transport Mgr 6.0 LIC per 2600/2800         | MWTM-6.XIT-2K-RTU               | Mobile Wireless Transport Mgr 6.X - 2600/2800 License       |

|                           |                                                             |                                                                       |                                                             |
|---------------------------|-------------------------------------------------------------|-----------------------------------------------------------------------|-------------------------------------------------------------|
| <b>MWTM-6.0IT-2K-RTU=</b> | Mobile Wireless Transport Mgr 6.0 - 2600/2800 License       | MWTM-6.XIT-2K-RTU                                                     | Mobile Wireless Transport Mgr 6.X - 2600/2800 License       |
| <b>MWTM-6.0IT-76-RTU</b>  | Mobile Wireless Transport Mgr 6.0 LIC per 7600              | MWTM-6.XIT-76-RTU                                                     | Mobile Wireless Transport Mgr 6.X - 7600 License            |
| <b>MWTM-6.0IT-76-RTU=</b> | Mobile Wireless Transport Mgr 6.0 - 7600 License            | MWTM-6.XIT-76-RTU                                                     | Mobile Wireless Transport Mgr 6.X - 7600 License            |
| <b>MWTM-6.0IT-7K-RTU</b>  | Mobile Wireless Transport Mgr 6.0 LIC per 72/73/7500        | MWTM-6.XIT-7K-RTU                                                     | Mobile Wireless Transport Mgr 6.X - 7200/7300/7500 Lic      |
| <b>MWTM-6.0IT-7K-RTU=</b> | Mobile Wireless Transport Mgr 6.0 - 7200/7300/7500 Lic      | MWTM-6.XIT-7K-RTU                                                     | Mobile Wireless Transport Mgr 6.X - 7200/7300/7500 Lic      |
| <b>MWTM-6.0IT-P5-RTU</b>  | Mobile Wireless Transport Mgr 6.0 LIC per 7500 Port Adapter | MWTM-6.XIT-P5-RTU                                                     | Mobile Wireless Transport Mgr 6.X - 7500 Port Adapter Lic   |
| <b>MWTM-6.0IT-P5-RTU=</b> | Mobile Wireless Transport Mgr 6.0 - 7500 Port Adapter Lic   | MWTM-6.XIT-P5-RTU                                                     | Mobile Wireless Transport Mgr 6.X - 7500 Port Adapter Lic   |
| <b>MWTM-6.0IT-PA-RTU</b>  | Mobile Wireless Transport Mgr 6.0 LIC per 7600 Port Adapter | MWTM-6.XIT-PA-RTU                                                     | Mobile Wireless Transport Mgr 6.X LIC per 7600 Port Adapter |
| <b>MWTM-6.0IT-PA-RTU=</b> | Mobile Wireless Transport Mgr 6.0 - 7600 Port Adapter Lic   | MWTM-6.XIT-PA-RTU                                                     | Mobile Wireless Transport Mgr 6.X LIC per 7600 Port Adapter |
| <b>MWTM-6.0IT-STBY-K9</b> | Mobile Wireless Transport Mgr 6.0 Standby Mode SW Lic       | MWTM-6.XIT-STBY-K9                                                    | Mobile Wireless Transport Mgr 6.X Standby Mode SW Lic       |
| <b>MWTM-6.0RA-STBY-K9</b> | Mobile Wireless Transport Mgr 6.0 RANO Standby Mode SW Lic  | MWTM-6.XRA-STBY-K9                                                    | Mobile Wireless Transport Mgr 6.X RANO Standby Mode SW Lic  |
| <b>MWTM-6.0SEF-F-RTU</b>  | Mobile Wireless TM 6.0.x - Fault Mgmt. 1 Lic per mSEF Card  | There is currently no replacement product available for this product. |                                                             |
| <b>MWTM-6.0SF-UF-RTU</b>  | Mobile Wireless Transp Mgr 6.0.x mSEF MWFM Upgrade Lic      | There is currently no replacement product available for this product. |                                                             |
| <b>MWTM6.0SF-76-RTU</b>   | Mobile Wireless Transport Mgr 6.0.x mSEF 7600 License       | MWTM6.XSF-76-RTU                                                      | Mobile Wireless Trans Mgr 6.x mSEF 7600 License             |
| <b>MWTM6.0SF-HABL-RTU</b> | Mobile Wireless Transport Mgr 6.0.x eHA Bundle License      | There is currently no replacement product available for this product. |                                                             |

## Product Migration Options

Customers are encouraged to migrate to the Cisco Mobile Wireless Transport Manager 6.1.

Information about this product can be found at: <http://www.cisco.com/go/mwtm>.

Service prices for Cisco products are subject to change after the product End of Sale date.

## For More Information

For more information about the Cisco Mobile Wireless Transport Manager 6.1, visit

<http://www.cisco.com/go/mwtm>, or contact your local account representative.

To request information about the Cisco Mobile Wireless Transport Manager 6.1, send an e-mail to [cs-mwtm@cisco.com](mailto:cs-mwtm@cisco.com).

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV  
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

CCDE, CCENT, Cisco Eos, Cisco HealthPresence, the Cisco logo, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, Cisco WebEx, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0812R)