

## End-of-Sale and End-of-Life Announcement for the CiscoWorks Interface Configuration Manager 1.0

EOL6499

Cisco<sup>®</sup> announces the end-of-sale and end-of life dates for the CiscoWorks Interface Configuration Manager 1.0. The last day to order the affected product(s) is February 11, 2009. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the CiscoWorks Interface Configuration Manager 1.0

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 11, 2008
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms.  The product is no longer for sale after this date.	February 11, 2009
End of SW Maintenance Releases Date: App. SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	February 11, 2010
End of Service Contract Renewal Date: App. SW	The last date to extend or renew a service contract for the product.	August 8, 2011
Last Date of Support: App. SW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	February 10, 2012

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
CWICM-1.0-BASE-K9	CiscoWorks Interface Configuration Mgr. 1.0 Base SW Kit
CWICM-10-100K-LIC	CiscoWorks Interface Configuration Mgr. 1.0 Add 100K ports
CWICM-10-100K-LIC=	CiscoWorks Interface Configuration Mgr. 1.0 Add 100K ports
CWICM-10-15K-LIC	CiscoWorks Interface Configuration Mgr. 1.0 Add 15K ports
CWICM-10-15K-LIC=	CiscoWorks Interface Configuration Mgr. 1.0 Add 15K ports
CWICM-10-50K-LIC	CiscoWorks Interface Configuration Mgr. 1.0 Add 50K ports
CWICM-10-50K-LIC=	CiscoWorks Interface Configuration Mgr. 1.0 Add 50K ports
CWICM-10-5K-LIC	CiscoWorks Interface Configuration Mgr. 1.0 Add 5K ports
CWICM-10-5K-LIC=	CiscoWorks Interface Configuration Mgr. 1.0 Add 5K ports

## **Product Migration Options**

There is no replacement available for the CiscoWorks Interface Configuration Manager 1.0 at this time.

Service prices for Cisco products are subject to change after the product End of Sale date.

## For More Information

For more information about the Cisco End-of-Life Policy, go to: <a href="http://www.cisco.com/en/US/products/pr

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, Cisco WebEx, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0809R)

Printed in USA C51-506349-00 11/08