



End-of-Life Notice, No. 2957

End-of-Sale and End-of-Life Announcement for the Cisco ONS 15454 Triple Play Bundles

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® ONS 15454 Triple Play Bundles. The last day to order the affected product is November 1, 2005. This announcement pertains to the specified bundle part numbers only and not to any other part of the Cisco ONS 15454 platform. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement and relevant information for migrating to the replacement product.

Table 1. End-of-Life Milestones and Dates for the Cisco ONS 15454 Triple Play Bundles

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	August 1, 2005
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 1, 2005
Last Ship Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	February 1, 2006
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	No product is being discontinued as a result of this announcement.
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	Support provided as part of the standard services for the bundle's individual components and support contract for the Cisco ONS 15454 and 15454E.
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.	
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Numbers	Replacement Product Description
15454-2.5G-TC2SK	Triple Play Bundle—Contains two XC-VT and two TCC2 cards	(2x) 15454-XC-VT= (2x) 15454-TCC2=	Standard equipment part numbers
15454-10G-TC-SK	Triple Play Bundle—Contains two XC-10G and two TCC2 cards	(2x) 15454-XC-10G= (2x) 15454-TCC2=	Standard equipment part numbers
15454-DS1-14-SK	Triple Play Bundle—Contains two DS1-14 cards	(2x) 15454-DS1-14=	Standard equipment part numbers
15454-G1K-SK	Triple Play Bundle—Contains two G1K-4 cards	(2x) 15454-G1K-4=	Standard equipment part numbers
15454E-2.5GTC2PSK	Triple Play Bundle—Contains two TCC2P and two XC-VXL-2.5G cards, ETSI	(2x) 15454E-TCC2P= (2x) 15454E-XC-VXL-2.5G=	Standard equipment part numbers

End-of-Sale Product Part Number	Product Description	Replacement Product Part Numbers	Replacement Product Description
15454E-10GTC2PSK	Triple Play Bundle—Contains two TCC2P and two XC-VXL-10G cards, ETSI	(2x) 15454E-TCC2P= (2x) 15454E-XC-VXL-10G=	Standard equipment part numbers
15454E-L16.2-1-SK	Triple Play Bundle—Contains two L16.2-1 cards, ETSI	(2x) 15454E-L16.2-1=	Standard equipment part numbers
15454E-S4.1-4-SK	Triple Play Bundle—Contains two S4.1-4 cards, ETSI	(2x) 15454E-L4.1-4=	Standard equipment part numbers
15454E-S16.1-1-SK	Triple Play Bundle—Contains two S16.1-1 cards, ETSI	(2x) 15454E-S16.1-1=	Standard equipment part numbers
15454E-2E1-42	Triple Play Bundle—Contains two E1-42 cards, ETSI	(2x) 15454E-E1-42=	Standard equipment part numbers

Product Migration Options

The recommended replacement for the Cisco ONS 15454 Triple Play Bundles is the Cisco ONS 15454 standard equipment part numbers.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

For More Information

For more information about the Cisco ONS 15454 Multiservice Provisioning Platform, visit:

<http://cisco.com/en/US/products/hw/optical/ps2006/index.html> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R)
Pa/LW8745 07/05

Printed in the USA

