



End-of-Sale and End-of-Life Announcement for the Cisco ONS 15305 Multiservice Customer Access Platform Release 1.X

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® ONS 15305 Release 1.x software and hardware. The last day to order the affected products is January 31, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until January 31, 2009, for the application software and January 31, 2011, for the hardware and OS.

Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement. Customers are encouraged to migrate to Cisco ONS 15305 Release 2.x or later, which is a superset of the products supported with Release 1.x and provides a more effective solution. Information about the replacement products can be found at:

<http://www.cisco.com/en/US/products/hw/optical/ps2001/ps5381/index.html>.

Table 2 provides relevant information for migrating to the replacement products.

Table 1. End-of-Life Milestones and Dates for the Cisco ONS 15305 Release 1.x Hardware, OS, and Application

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	August 1, 2005
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 31, 2006
Last Ship Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 1, 2006
End of SW Maintenance Release	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	January 31, 2007
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect. (Applies to hardware and OS only.)	January 31, 2007
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 31, 2007
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.	Application software: April 30, 2008 Hardware and OS: April 30, 2010
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	Application software: January 31, 2009 Hardware and OS: January 31, 2011

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
15305-SA-R1.1.1=	Cisco ONS 15305 Shelf Assembly, Software 1.1.1, includes Ship-Kit (spare)	15305-SA-R2.0.0=	Cisco ONS 15305 Shelf Assembly, Software 2.0.0, includes Ship-Kit (spare)
15305-SA-R1.1.0=	Cisco ONS 15305 Shelf Assembly, Software 1.1.0, includes Ship-Kit (spare)	15305-SA-R2.0.0=	Cisco ONS 15305 Shelf Assembly, Software 2.0.0, includes Ship-Kit (spare)
15305-SA-R1.0.0=	Cisco ONS 15305 Shelf Assembly, Software 1.0.0, includes Ship-Kit (spare)	15305-SA-R2.0.0=	Cisco ONS 15305 Shelf Assembly, Software 2.0.0, includes Ship-Kit (spare)
15305-DOC1.0.CD=	Cisco ONS 15305 System Documentation 1.0.0, English, CD (spare)	15305-DOC2.0.CD=	Cisco ONS 15305 System Documentation 2.0.0, English, CD (spare)
15305-R1.1.1SWCD=	Cisco ONS 15305 Software 1.1.1 Feature Package, CD (spare)	15305-R2.0.0SWCD=	Cisco ONS 15305 Software 2.0.0 Feature Package, CD (spare)
15305-R1.1.0SWCD=	Cisco ONS 15305 Software 1.1.0 Feature Package, CD (spare)	15305-R2.0.0SWCD=	Cisco ONS 15305 Software 2.0.0 Feature Package, CD (spare)
15305-R1.0.0SWCD=	Cisco ONS 15305 Software 1.0.0 Feature Package, CD (spare)	15305-R2.0.0SWCD=	Cisco ONS 15305 Software 2.0.0 Feature Package, CD (spare)
15305-R1.2.0-CEC=	Cisco ONS 15305 Cisco Edge Craft Management Tool, 1.2.0 (spare)	15305-R2.0.0-CEC=	Cisco ONS 15305 Cisco Edge Craft Management Tool, 2.0.0 (spare)
15305-R1.1.0-CEC=	Cisco ONS 15305 Cisco Edge Craft Management Tool, 1.1.0 (spare)	15305-R2.0.0-CEC=	Cisco ONS 15305 Cisco Edge Craft Management Tool, 2.0.0 (spare)
15305-GE-2S1.1-8=	Cisco ONS 15305 2 x Gigabit Ethernet (GE) Service Module with Mapper and 8 x S1.1-LC (2 slots) (spare)	15305-GE-2-W=	Cisco ONS 15305 2 x GE Service Module with WAN Mapper, Small Form-Factor Pluggable (SFP) connectors (spare)
15305-E100S1.1-8=	Cisco ONS 15305 8 Fast Ethernet (FE) Service Module with Mapper and 8 x S1.1-LC (2 slots) (spare)	15305-E100-8-W=	Cisco ONS 15305 8 x FE 10/100BASE-TX Service Module with WAN Mapper (spare)
15305-SHIPKIT-1.1=	Cisco ONS 15305 Ship-Kit 1.x (spare)	15305-SHIPKIT=	Cisco ONS 15305 Ship-Kit (spare)

NOTE: Hardware, OS, and application software items have separate milestones for end of service contract renewal and last day of support as shown in Table 1. Application software includes the 15305-Rx.x.x-CEC items shown in Table 2 with respective milestone dates indicated in Table 1.

Product Migration Options

The recommended replacement for the Cisco ONS 15305 Release 1.x items are the Release 2.x items shown in Table 2.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

For More Information

For more information about the Cisco ONS 15305 Multiservice Customer Access Platform, visit:

<http://www.cisco.com/en/US/products/hw/optical/ps2001/ps5381/index.html> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/pcgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

