



End-of-Sale and End-of-Life Announcement for the Cisco UCS 6100 Series Fabric Interconnects and Cisco UCS 2100 Series IO Modules

EOL8320—Amended

Cisco announces the end-of-sale and end-of life dates for the Cisco UCS 6100 Series Fabric Interconnects and Cisco UCS 2100 Series IO Modules. The last day to order the affected product(s) is March 1, 2013. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco UCS 6100 Series Fabric Interconnects and Cisco UCS 2100 Series IO Modules

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	June 1, 2012
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 1, 2013
Last Ship Date: HW	The last-possible ship date that can requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 30, 2013
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	March 1, 2014
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	March 1, 2014
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	March 1, 2014
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	May 29, 2017
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	March 31, 2018

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
N10-S6100	UCS 6120XP 20-port Fabric Interconnect/0 PSU/2 fans/no SFP+	UCS-FI-6248UP	UCS 6248UP 1RU Fabric Int/No PSU/32 UP/ 12p LIC	—
N10-S6100-UPG	UCS 6120XP 20-port Fabric Interconnect/0 PSU/2 fans/no SFP+	UCS-FI-6248UP-UPG	UCS 6248UP 1RU Fabric Int/No PSU/32 UP/ 12p LIC	—
N10-S6200	UCS 6140XP 40-port Fabric Interconnect/0 PSU/5 fans/no SFP+	UCS-FI-6248UP	UCS 6248UP 1RU Fabric Int/No PSU/32 UP/ 12p LIC	—
		UCS-FI-6296UP	UCS 6296UP 2RU Fabric Int/No PSU/48 UP/ 18p LIC	—
N10-S6200-UPG	UCS 6140XP 40-port Fabric Interconnect/0 PSU/5 fans/no SFP+	UCS-FI-6248UP-UPG	UCS 6248UP 1RU Fabric Int/No PSU/32 UP/ 12p LIC	—
		UCS-FI-6296UP-UPG	UCS 6296UP 2RU Fabric Int/No PSU/48 UP/ 18p LIC	—
N10-E0060, N10-E0060=	6-port 8Gb FC/Expansion module/UCS 6100 Series	UCS-FI-E16UP, UCS-FI-E16UP=	UCS 6200 16-port Expansion module/16 UP/ 8p LIC	—
N10-E0080, N10-E0080=	8-port 4Gb FC/Expansion module/UCS 6100 Series	UCS-FI-E16UP, UCS-FI-E16UP=	UCS 6200 16-port Expansion module/16 UP/ 8p LIC	—
N10-E0440, N10-E0440=	4-port 10 GE/4-port 4Gb FC/Expansion module/UCS 6100 Series	UCS-FI-E16UP, UCS-FI-E16UP=	UCS 6200 16-port Expansion module/16 UP/ 8p LIC	—
N10-E0600, N10-E0600=	6-port 10 GE/Expansion module/UCS 6100 Series	UCS-FI-E16UP, UCS-FI-E16UP=	UCS 6200 16-port Expansion module/16 UP/ 8p LIC	—
N10-FAN1=	Fan module for UCS 6120XP Fabric Interconnect	UCS-FAN-6248UP=	UCS 6248UP Fan Module	—
N10-FAN2=	Fan module for UCS 6140XP Fabric Interconnect	UCS-FAN-6296UP=	UCS 6296UP Fan Module	—
N10-PAC1-550W, N10-PAC1-550W=	550W power supply unit for UCS 6120XP/100-240VAC	UCS-PSU-6248UP-AC, UCS-PSU-6248UP-AC=	UCS 6248UP Power Supply/100-240VAC	—
N10-PAC2-750W, N10-PAC2-750W=	750W power supply unit for UCS 6140XP/100-240VAC	UCS-PSU-6296UP-AC, UCS-PSU-6296UP-AC=	UCS 6296UP Power Supply/100-240VAC	—
N10-S1BLKP, N10-S1BLKP=	Power supply unit blanking panel for UCS 6120XP	There is currently no replacement product available for this product.		
N10-S2BLKP, N10-S2BLKP=	Power supply unit blanking panel for UCS 6140XP	There is currently no replacement product available for this product.		
N10-SACCA, N10-SACCA=	Accessory kit for UCS 6120XP Fabric Interconnect	UCS-ACC-6248UP, UCS-ACC-6248UP=	UCS 6248UP Chassis Accessory Kit	—
		UCS-ACC-6296UP, UCS-ACC-6296UP=	UCS 6296UP Chassis Accessory Kit	—
N10-SACCB, N10-SACCB=	Accessory kit for UCS 6140XP Fabric Interconnect	UCS-ACC-6248UP, UCS-ACC-6248UP=	UCS 6248UP Chassis Accessory Kit	—
		UCS-ACC-6296UP, UCS-ACC-6296UP=	UCS 6296UP Chassis Accessory Kit	—
N10-SBLKE, N10-SBLKE=	Expansion module slot blanking panel for UCS 6100 Series	UCS-BLKE-6200, UCS-BLKE-6200=	UCS 6200 Series Expansion Module Blank	—
N20-I6584, N20-I6584=	UCS 2104XP Fabric Extender/4 external 10Gb ports	UCS-IOM-2204XP, UCS-IOM-2204XP=	UCS 2204XP I/O Module (4 External, 16 Internal 10Gb Ports)	—

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
		UCS-IOM-2208XP, UCS-IOM-2208XP=	UCS 2208XP I/O Module (8 External, 32 Internal 10Gb Ports)	—

Product Migration Options

Customers are encouraged to migrate to the Cisco UCS 6200 Series Fabric Interconnects and Cisco UCS 2200 Series IO Modules. Information about this product can be found at:

<http://www.cisco.com/en/US/products/ps11544/index.html>.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html

Customers may be able to continue to purchase the Cisco UCS 6100 Series Fabric Interconnects and Cisco UCS 2100 Series IO Modules through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to:

www.cisco.com/go/eos

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html

For More Information

For more information about the Cisco UCS 6200 Series Fabric Interconnects and Cisco UCS 2200 Series IO Modules, visit <http://www.cisco.com/en/US/products/ps11544/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html

For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA

C51-712410-02 10/12

© 2012 Cisco and/or its affiliates. All rights reserved. This document is Cisco Public.

Page 4 of 4