# 111111 CISCO

# End-of-Sale and End-of-Life Announcement for the Cisco 73GB 6Gb SAS 15K RPM SFF HDD **Mounted Drive Sled**

# EOL7924

Cisco announces the end-of-sale and end-of life dates for the Cisco 73GB 6Gb SAS 15K RPM SFF HDD Mounted Drive Sled. The last day to order the affected product(s) is December 12, 2011. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Milestone	Definition	Date
End-of-Llfe Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	September 12, 2011
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 12, 2011
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 11, 2012
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	December 11, 2012
End of Vulnerability/Security Support: HW	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	December 11, 2014
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	December 11, 2012
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 11, 2012
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	March 8, 2016
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 31, 2016

#### Table 1. End-of-Life Milestones and Dates for the Cisco 73GB 6Gb SAS 15K RPM SEE HDD Mounted Drive Sled

HW = Hardware

OS SW = Operating System Software App. SW = Application Software

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
A03-D073GC2	73GB 6Gb SAS 15K RPM SFF HDD/hot plug/drive sled mounted	A03-D146GC2	146GB 6Gb SAS 15K RPM SFF HDD/hot plug/drive sled mounted	
A03-D073GC2=	73GB 6Gb SAS 15K RPM SFF HDD/hot plug/drive sled mounted	A03-D146GC2=	146GB 6Gb SAS 15K RPM SFF HDD/hot plug/drive sled mounted	

### Table 2. Product Part Numbers Affected by This Announcement

# **Product Migration Options**

Customers are encouraged to migrate to the Cisco 146GB 6Gb SAS 15K RPM SFF HDD Mounted Drive Sled. Information about this product can be found at:

http://www.cisco.com/en/US/prod/collateral/ps10265/ps10280/data\_sheet\_c78-524797\_ps10280\_Products\_Data\_Sheet.html.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about\_cisco\_takeback\_recycling.html

### For More Information

For more information about the Cisco146GB 6Gb SAS 15K RPM SFF HDD Mounted Drive Sled, visit <u>http://www.cisco.com/en/US/products/ps10280/prod\_eol\_notices\_list.html</u>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products\_end-of-life\_policy.html

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod\_warranties\_listing.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html

# Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end\_of\_life\_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)

Printed in USA