



## End-of-Sale and End-of-Life Announcement for the Cisco 16GB DDR3-1066MHz Quad Rank RDIMM Memory

### EOL7999—Amended

Cisco announces the end-of-sale and end-of life dates for the Cisco 16GB DDR3-1066MHz Quad Rank RDIMM Memory. The last day to order the affected product(s) is February 20, 2012. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

**Table 1.** End-of-Life Milestones and Dates for the Cisco 16GB DDR3-1066MHz Quad Rank RDIMM Memory

| Milestone                                       | Definition                                                                                                                                                                                                                                                    | Date              |
|-------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| <b>End-of-Life Announcement Date</b>            | The date the document that announces the end of sale and end of life of a product is distributed to the general public.                                                                                                                                       | November 21, 2011 |
| <b>End-of-Sale Date</b>                         | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.                                                                                                                                 | February 20, 2012 |
| <b>Last Ship Date: HW</b>                       | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.                                                                                                                     | May 20, 2012      |
| <b>End of Routine Failure Analysis Date: HW</b> | The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.                                                                                                                              | February 19, 2013 |
| <b>End of New Service Attachment Date: HW</b>   | For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.                         | February 19, 2013 |
| <b>End of Service Contract Renewal Date: HW</b> | The last date to extend or renew a service contract for the product.                                                                                                                                                                                          | May 17, 2016      |
| <b>Last Date of Support: HW</b>                 | The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. | February 28, 2017 |

HW = Hardware    OS SW = Operating System Software    App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

| End-of-Sale Product Part Number | Product Description                                      | Replacement Product Part Number | Replacement Product Description                    | Additional Information |
|---------------------------------|----------------------------------------------------------|---------------------------------|----------------------------------------------------|------------------------|
| <b>A02-M316GB2-L</b>            | 16GB DDR3-1066MHz RDIMM/PC3-8500/quad rank/Low-Dual Volt | UCS-MR-1X162RY-A                | 16GB DDR3-1600-MHz RDIMM/PC3-12800/dual rank/1.35v | —                      |
| <b>A02-M316GB2-L=</b>           | 16GB DDR3-1066MHz RDIMM/PC3-8500/quad rank/Low-Dual Volt | UCS-MR-1X162RY-A=               | 16GB DDR3-1600-MHz RDIMM/PC3-12800/dual rank/1.35v | —                      |

## Product Migration Options

Customers are encouraged to migrate to the Cisco 16GB DDR3-1600MHz Dual Rank RDIMM memory.

Information about this product can be found at:

[http://www.cisco.com/en/US/products/ps10280/prod\\_eol\\_notices\\_list.html](http://www.cisco.com/en/US/products/ps10280/prod_eol_notices_list.html).

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html)

## For More Information

For more information about the Cisco 16GB DDR3-1600MHz Dual Rank RDIMM Memory, visit

[http://www.cisco.com/en/US/products/ps10280/prod\\_eol\\_notices\\_list.html](http://www.cisco.com/en/US/products/ps10280/prod_eol_notices_list.html), or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html)

For more information about the Cisco Product Warranties, go to:

[http://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](http://www.cisco.com/en/US/products/prod_warranties_listing.html)

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

[http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml)

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



---

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA

C51-693399-01 05/13

© 2013 Cisco and/or its affiliates. All rights reserved. This document is Cisco Public.

Page 3 of 3