

Product Bulletin No. EOL1007

# End-of-Sale and End-of-Life Announcement for the Cisco MDS 9500 Series 1900W DC, 2500W DC and 4000W AC/DC Power Supplies

Cisco Systems<sup>®</sup> announces the end-of-sale and end-of life dates for the Cisco<sup>®</sup> MDS 9500 Series 1900W DC, 2500W DC, and 4000W AC/DC Power Supplies. The last day to order the affected products is June 16, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until June 15, 2011. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	December 16, 2005
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 16, 2006
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	June 16, 2006
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	June 16, 2007
End of New Service Attachment Date	For equipment and software that is not covered by a service-and- support contract, this is the last date to order a new service-and- support contract or add the equipment and/or software to an existing service-and-support contract.	June 16, 2007
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.	September 11, 2010
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	June 15, 2011

Table 1. End-of-Life Milestones and Dates for the Cisco MDS 9500 Series 1900W DC, 2500W DC, 4000W AC/DC Power Supplies.

# Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
DS-CAC-4000W-INT	4000W AC Power Supply International
DS-CAC-4000W-INT=	4000W AC Power Supply International, Spare
DS-CAC-4000W-US	4000W AC Power Supply for US
DS-CAC-4000W-US=	4000W AC Power Supply for US, Spare
DS-CDC-1900W	1900W DC Power Supply
DS-CDC-1900W=	1900W DC Power Supply
DS-CDC-2500W	2500W DC Power Supply
DS-CDC-2500W=	2500W DC Power Supply, Spare
DS-CDC-4000W-INT	4000Watt DC Power Supply for US (cable attached)

End-of-Sale Product Part Number	Product Description
DS-CDC-4000W-INT=	4000Watt DC Power Supply for US (cable attached)
DS-CDC-4000W-US	4000Watt DC Power Supply for US (cable attached)
DS-CDC-4000W-US=	4000Watt DC Power Supply for US (cable attached)

# **PRODUCT MIGRATION OPTIONS**

There is no replacement product for the 1900W DC, 2500W DC, US and International 4000W DC, US and International 4000W AC power supplies at this time.

Cisco does not offer trade-in credits or a trade-in program.

## FOR MORE INFORMATION

For more information about the Cisco MDS 9500 Series 1900W DC, 2500W DC, and 4000W AC/DC Power Supplies, visit <a href="http://www.cisco.com/en/US/products/ps5990/index.html">http://www.cisco.com/en/US/products/ps5990/index.html</a> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod end of life.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice



### **Corporate Headquarters**

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 526-4100 European Headquarters Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

#### Americas Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883

# Asia Pacific Headquarters

Cisco Systems, Inc. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com Tel: +65 6317 7777 Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at** <u>www.cisco.com/go/offices</u>.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) 205277.L\_ETMG\_LR\_12.05

© 2005 Cisco Systems, Inc. All rights reserved. Important notices, privacy statements, and trademarks of Cisco Systems, Inc. can be found on cisco.com. Page 3 of 3