

Product Bulletin No. EOL4109

Product Identification Change Announcement for certain Cisco SFS 3000 Series, SFS 7000 Series, and Accessories

Cisco Systems[®] announces the end-of-sale and end-of life dates for certain Cisco SFS 3000 Series, SFS 7000 Series, and Accessories in the European Union countries. The last day to order the affected product is May 30, 2006. European Union countires customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until November 30, 2011.

Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the new product identifications that annotate products with identical form, fit or function of the end-of-sale/end-of-life products. Table 2 provides relevant information for migrating to the replacement product.

Milestone	Definition	Date
European Union Countries End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 30, 2006
European Union Countries End of routine failure analysis date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	November 30, 2007
European Union Countries End of new service attachment date	of new For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	
European Union Countries End of service contract renewal date	ies End of service The last date to extend or renew a service contract for the product.	
European Union Countries Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	November 30, 2011

Table 1. End-of-Life Milestones and Dates for certain Cisco SFS 3000 Series, SFS 7000 Series, and Accessories

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
CAB-SFS7008-SER=	Cisco SFS 7008 Serial Cable Kit	CAB-SFS7008P-SER=	Cisco SFS 7008P Serial Cable Kit
FAN-SFS3001=	Cisco SFS 3001 FAN	FAN-SFS3012R=	Cisco SFS 3012R (RoHS) Blower Module
FAN-SFS3012=	Cisco SFS 3012 Blower Module	FAN-SFS3012R=	Cisco SFS 3012R (RoHS) Blower Module
FAN-SFS7008=	Cisco SFS 7008 Fan Tray	FAN-SFS7008P=	Cisco SFS 7008P Fan Tray
PWR-SFS3001=	Cisco SFS 3001 Power Supply	PWR-SFS3012R=	Cisco SFS 3012R (RoHS) Power Supply
PWR-SFS3012=	Cisco SFS 3012 Power Supply	PWR-SFS3012R=	Cisco SFS 3012R (RoHS) Power Supply
PWR-SFS7000=	Cisco SFS 7000 Power Supply/Cooling	PWR-SFS7000P=	Cisco SFS 7000P Power Supply/Cooling
PWR-SFS7008=	Cisco SFS 7008 Power Supply	PWR-SFS7008P=	Cisco SFS 7008P Power Supply
SFS-3001-4X012-SK9	Cisco SFS 3001 Multifabric Server Switch	SFS3012R-4X24-SK9	Cisco SFS 3012 Multifabric Server Switch (Std, RoHS)
SFS-3012-4X024-HK9	Cisco SFS 3012 Multifabric Server Switch (HA)	SFS3012R-4X24-HK9	Cisco SFS 3012 Multifabric Server Switch (HA, RoHS)

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
SFS-3012-4X024-SK9	Cisco SFS 3012 Multifabric Server Switch (standard)	SFS3012R-4X24-SK9	Cisco SFS 3012 Multifabric Server Switch (Std, RoHS)
SFS-3012-MFM-K9=	Cisco SFS 3012 Management Interface Module	SFS-3012R-MFM-K9=	Cisco SFS 3012R (RoHS) Management Interface Module
SFS-7000-4X024-SK9	Cisco SFS 7000 IB Server Switch, 24 InfiniBand ports	SFS7000P-SK9	Cisco SFS 7000P IB Server Switch, 24 InfiniBand Pwr Ports
SFS-7008-4X048-SK9	Cisco SFS 7008 IB Server Switch, 48 InfiniBand ports (std)	SFS7008P	Cisco SFS 7008P Switch Chassis
SFS-7008-4X072-SK9	Cisco SFS 7008 IB Server Switch, 72 InfiniBand ports (std)	SFS7008P	Cisco SFS 7008P Switch Chassis
SFS-7008-4X096-SK9	Cisco SFS 7008 IB Server Switch, 96 InfiniBand ports (std)	SFS7008P	Cisco SFS 7008P Switch Chassis
SFS-7008-BLANK=	Cisco SFS 7008 Blanking Panels	SFS7008P	Cisco SFS 7008P Switch Chassis
SFS-7008-BZEL=	Cisco SFS 7008 Bezel	 SFS-7008P-SBLNK= SFS-7008P-PBLNK= SFS-7008P-FBLNK= SFS-7008P-MBLNK= 	 Cisco SFS 7008P SFM Blanking Panels Cisco SFS 7008P Power Supply Blanking Panels Cisco SFS 7008P Fan Module Blanking Panels Cisco SFS 7008P Management I/O Blanking Panels
SFS-7008-CHID=	Cisco SFS 7008 Chassis ID Card	SFS-7008P-CHID=	Cisco SFS 7008P Chassis ID Card
SFS-7008-HA-K9=	Cisco SFS 7008 IB Server Switch HA Package	SFS7008P-HA	Cisco SFS 7008P High Availability Kit
SFS-7008-K9	Cisco SFS 7008 Switch Chassis	SFS7008P	Cisco SFS 7008P Switch Chassis
SFS-7008-MFM-K9=	Cisco SFS 7008 Management Inferface Module	SFS7008P-MFM-K9=	Cisco SFS 7008P Management Inferface Module
SFS-7008-RKIT=	Cisco SFS 7008 Rail Kit	SFS-7008P-RKIT=	Cisco SFS 7008P Rail Kit
SFS-7008-SFM-K9=	Cisco SFS 7008 Switch Fabric Module	SFS7008P-SFM-K9=	Cisco SFS 7008P Switch Fabric Module
SFS-7012	Cisco SFS 7012 InfiniBand Server Switch 144 Port Chassis	SFS-7012P	Cisco SFS 7012P IB Server Switch— 144 Port Std Config
SFS-7012-X	Cisco SFS 7012 IB Server Switch— 108 Port Upgrade Config	SFS-7012P-X	Cisco SFS 7012P IB Server Switch— 108 Port Upgrade Config
SFS-7024	Cisco SFS 7024 InfiniBand Server Switch 288 Port Chassis	SFS-7024P	Cisco SFS 7024P IB Server Switch— 288 Port Std Config
SFS-7024-X	Cisco SFS 7024 IB Server Switch— 156 Port Upgrade Config	SFS-7024P-X	Cisco SFS 7024P IB Server Switch— 156 Port Upgrade Config

PRODUCT MIGRATION OPTIONS

The recommended replacement for EOS / EOL product identification Cisco SFS 3000 Series, SFS 7000 Series, and Accessories is the new set of product identifications for Cisco SFS 3000 Series, SFS 7000 Series, and Accessories.

Customers are encouraged to migrate to the new product identifications for Cisco SFS 3000 Series, SFS 7000 Series, and accessories. Information about this product can be found at http://www.cisco.com/en/US/products/ps6418/index.html. The new product identifications of Cisco SFS 3000 Series, SFS 7000 Series, and accessories have the same form, fit, and function as their older- product-identification counterparts.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to <u>http://www.cisco.com/go/tradein/</u>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description.html

FOR MORE INFORMATION

- For more information about the new product identifications for Cisco SFS 3000 Series, SFS 7000 Series, and Accessories, visit http://www.cisco.com/en/US/products/ps6418/index.html, contact your local account representative, or send an e-mail to ask_sfs@cisco.com.
- For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html
- To subscribe to receive end-of-life/end-of-sale information, go to: <u>http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice</u>





Corporate Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 526-4100 European Headquarters Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100 Americas Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883 Asia Pacific Headquarters Cisco Systems, Inc. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com Tel: +65 6317 7777 Fax: +65 6317 7779

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco.com Website at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco IOS, Cisco Forses, Cisco Systems, CajaDrive, GigaDrice, GigaDrack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

Printed in USA

C51-351091-00 05/06