

Change in Product Part Number Announcement for the Tandberg MCU 4200 Series - non-A Version

EOL7949

Cisco announces a change in product part numbers for the Tandberg MCU 4200 Series - non-A Version. This is a product part number change only announcement. Customers will experience no change in functionality when using the new product part numbers. The new product part numbers are designed to simplify the customer ordering process. The last day to order the affected product using the current product part numbers is October 25, 2010. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until otherwise specified in the end-of-life announcement for the new product part numbers. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Table 1. End-of-Life Milestones and Dates for the Tandberg MCU 4200 Series - non-A Version

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	July 26, 2010
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 25, 2010
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 23, 2011

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CTI-MCU-194203-K9	194203 Tandberg MCU 4200	CTI-4203-MCU-K9	MCU-4203 6 Port Enterprise MCU	-
CTI-MCU-194205-K9	194205 Tandberg MCU 4205	CTI-4205-MCU-K9	MCU 4205 - 12 Port Enterprise MCU	-
CTI-MCU-194210-K9	194210 Tandberg MCU 4210	CTI-4210-MCU-K9	MCU-4210 20 Port Enterprise MCU	-
CTI-MCU-194215-K9	194215 Tandberg MCU 4215	CTI-4215-MCU-K9	MCU-4215 30 Port Enterprise MCU	-
CTI-MCU-194220-K9	194220 Tandberg MCU 4220	CTI-4220-MCU-K9	MCU-4220 40 Port Enterprise MCU	-

Product Migration Options

This is a product part number change only. Customers will experience no change in functionality when using the new product IDs. The new product IDs are designed to simplify the ordering process.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco TelePresence MCU 4200 Series, visit http://www.cisco.com/en/US/prod/collateral/ps7060/ps11305/ps11317/ps11342/data_sheet_c78-627468.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products-end-of-life-policy.html.

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end of life rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

cisco.

Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

 $Cisco\ has\ more\ than\ 200\ offices\ worldwide.\ Addresses,\ phone\ numbers,\ and\ fax\ numbers\ are\ listed\ on\ the\ Cisco\ Website\ at\ www.cisco.com/go/offices.$

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-688998-01 12/11