ılıılı cısco

End-of-Sale and End-of-Life Announcement for the Tandberg Legacy Miscellany for Collaborator MXP, Educator MXP, 3000 MXP, Custom Integrator, and Collier Educator

EOL8078

Cisco announces the end-of-sale and end-of-life dates for the Tandberg Legacy Miscellany for Collaborator MXP, Educator MXP, 3000 MXP, Custom Integrator, and Collier Educator. The last day to order the affected product(s) is January 30, 2010. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	August 1, 2009
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 30, 2010
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 30, 2010
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	January 30, 2011
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 30, 2011
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	April 27, 2014
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	January 31, 2015

 Table 1.
 End-of-Life Milestones and Dates for the Tandberg Legacy Miscellany for Collaborator MXP, Educator MXP, 3000

 MXP, Custom Integrator, and Collier Educator

HW = Hardware

lware

OS SW = Operating System Software App. SW = Application Software

,			
End-of-Sale Product Part Number	Product Description		
CTS-3000-B5003461	B5003461LE Tandberg 3000 MXP w/50 inch Plasma		
CTS-AMP-500687=	500687 VGA Distribution Amplifier		
CTS-CAB-501046=	501046 DVI-male to DVI-male cable		
CTS-CAB-5S1630048=	5S163-0048 AMP TO SPEAKER CABLE, 48 inch		
CTS-CLB-501761=	501761 Collaborator Outboard Assembly		
CTS-CLB-501770=	501770 Collaborator Control Module		
CTS-DNAM-1133554U=	1133554U DNAM Module		
CTS-EDU-B5009126N	B5009126N Educator MXP HD with 50 plasma display		
CTS-NEC-501778=	501778 NEC 60XP10-BK 60 PLASMA DISPLAY		
CTS-SMRT-502070=	502070 SMART Display Frame		
CTS-SPRK-501717=	501717 Speaker Bar For NEC 60 inch Plasma		
CTS-TAC-114150NROK	114150N, 114150ROK TANDBERG Tactical MXP V.35, NTSC		

Table 2. Product Part Numbers Affected by This Announcement

Product Migration Options

There is no replacement available for the Tandberg Legacy Miscellany for Collaborator MXP, Educator MXP, 3000 MXP, Custom Integrator, and Collier Educator at this time.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Tandberg Legacy Miscellany for Collaborator MXP, Educator MXP, 3000 MXP, Custom Integrator, and Collier Educator through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <u>http://www.cisco.com/go/eos</u>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod warranties listing.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: <u>http://www.cisco.com/web/feeds/products/end_of_life_rss.xml</u>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA