

End-of-Sale and End-of-Life Announcement for the Cisco 871 Integrated Services Router

EOL6925

Cisco announces the end-of-sale and end-of life dates for the Cisco 871 Integrated Services Router. The last day to order the affected product(s) is July 15, 2010. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco 871 Integrated Services Router

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	January 14, 2010
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 15, 2010
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 13, 2010
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	July 15, 2013
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	July 15, 2011
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 15, 2011
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	October 10, 2014
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	

HW = Hardware OS SW = Operating System Software App. SW = Application Software

 Table 2.
 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
CISCO871-K9	Dual Ethernet Security Router	CISCO881-K9	Cisco 881 Ethernet Sec Router
CISCO871-SEC-K9	Cisco 871 Security Bundle with Advanced IP Services	CISCO881-SEC-K9	Cisco 881 Ethernet Sec Router w/ Adv IP Services
CISCO871W-G-A-K9	Dual E Security Router with 802.11g FCC Compliant	CISCO881W-GN-A-K9	Cisco 881 Ethernet Sec Router 802.11n FCC Comp
CISCO871W-G-E-K9	Dual E Security Router with 802.11g ETSI Compliant	CISCO881W-GN-E-K9	Cisco 881 Ethernet Sec Router 802.11n ETSI Comp
CISCO871W-G-J-K9	Dual E Security Router with 802.11g Japan Compliant	CISCO881W-GN-P-K9	Cisco 881 Ethernet Sec Router 802.11n Japan Comp

Product Migration Options

Customers are encouraged to migrate to the Cisco 881 Integrated Services Router. Information about this product can be found at: http://www.cisco.com/en/US/products/ps9556/index.html.

Customers can use the Cisco Technology Migration Program (TMP) to trade-in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at http://www.cisco.com/web/partners/pr11/incentive/tmp/index.html

Customers may be able to continue to purchase the Cisco 871 Integrated Services Router through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: www.cisco.com/go/eos

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html

For More Information

For more information about the Cisco 881 Integrated Services Router, visit http://www.cisco.com/en/US/products/ps9556/index.html, or contact your local account representative.

To request information about the Cisco 881 Integrated Services Router, send an e-mail to cs-800@cisco.com.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml



Americas Headquariers Cieco Systems, Inc. Ser Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pic. Ltd. Singscore Europe Headquarters Cleop Systems International RV Amatercam, The Natherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

GODE, COENT, COS), Gisco Hos Cisco Hoshit-Pesence, Cisco Irentifort, the Cisco logo, Cisco Nurse Garneri, Cisco Philes, Cisco Stacki-Power, Cisco

All other tradements mentioned in this document or website are the property of their respective dwners. The use of the word partner does not imply a partnership teleforeint between Claus and any other company, (091018)

Printed in USA C51-577888-00 1/10