

# End-of-Sale and End-of-Life Announcement for the Select Cisco 1700 and 7000 Series Router Cables

#### EOL8027

Cisco announces the end-of-sale and end-of life dates for the Select Cisco 1700 and 7000 Series Router Cables. The last day to order the affected product(s) is March 20, 2012. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Select Cisco 1700 and 7000 Series Router Cables

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	December 20, 2011
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 20, 2012
Last Ship Date: Accessory	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	June 18, 2012

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
C1721-APISP-10	CISCO1721 10 Pack for Asia-Pac: QTY 10 MUST BE ORDERED!
C1721-MS	1721 bundle with WIC-1DSU-T1-V2, IP Base, 32M FL, 64 MB DR
C1721-T1	1721 T1 bundle
CAB-25AS-FDTE	Female DB-25 Terminal Connector
CAB-25AS-FDTE=	Female DB-25 Terminal Connector
CAB-OCT-232-FC	8 Lead Octal Cable and 8 Female RS232/V.24 DCE Connectors
CAB-OCT-232-FC=	8 Lead Octal Cable and 8 Female RS232/V.24 DCE Connectors
CAB-OCT-232-MT	8 Lead Octal Cable and 8 Male RS232/V.24 DTE Connectors
CAB-OCT-232-MT=	8 Lead Octal Cable and 8 Male RS232/V.24 DTE Connectors
CAB-OCT-X21-FC	8 Lead Octal Cable and 8 Female X21 DCE Connectors
CAB-OCT-X21-FC=	8 Lead Octal Cable and 8 Female X21 DCE Connectors
CAB-OCT-X21-MT	8 Lead Octal Cable and 8 Male X21 DTE Connectors
CAB-OCT-X21-MT=	8 Lead Octal Cable and 8 Male X21 DTE Connectors
CAB-OCTAL-FDTE	8 Lead Octal Cable and 8 Female DB-25 Terminal Connectors

End-of-Sale Product Part Number	Product Description
CAB-OCTAL-FDTE=	8 Lead Octal Cable and 8 Female DB-25 Terminal Connectors
CISCO1721-2T-LA	Cisco 1721 chassis w/ WIC-2T
CISCO1721-LA10	1721bundle w/WIC-1T for LATAM/10-pack must be ordered
CISCO1721-SER-ISDN	Bundle includes: Cisco1721, WIC-1T, WIC-1B-S/T and CAB-V35MT

### **Product Migration Options**

There is no replacement available for the Select Cisco 1700 and 7000 Series Router Cables at this time.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about cisco takeback recycling.html

#### For More Information

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products\_end-of-life\_policy.html

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod\_warranties\_listing.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html

#### Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: <a href="http://www.cisco.com/web/feeds/products/end">http://www.cisco.com/web/feeds/products/end</a> of life rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

## cisco.

Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-694114-00 11/11