ılıılı cısco

Cisco has retracted the EOS and EOL announcement for the STM-1 Bundles and Modules for the Cisco Integrated Services Router Generation 2

EOL7933 - Amended

Cisco STM-1 Bundles and Modules for the Cisco Integrated Services Router Generation 2 have been restored to their supported status. The products impacted by this announcement are in Table 1 below.

End-of-Sale Product Part Number	Product Description
C3925-STM-1-SM/K9	3925 w/ SPE100 3GE, 4EHWIC, 4DSP, 2SM, w/ SM-1-STM1-SM-C
C3925E-STM-1-SM/K9	3925E w/ SPE200 4GE, 3EHWIC, 3DSP, 2SM, w/ SM-1-STM1-SM-C
C3945-STM-1-SM/K9	3945 w/ SPE150 3GE, 4EHWIC, 4DSP, 4SM, w/ SM-1-STM1-SM-C
C3945E-STM-1-SM/K9	3945E w/ SPE250 4GE, 3EHWIC, 3DSP, 4SM, w/ SM-1-STM1-SM-C
SM-1-STM1-MM-C	Channelized STM-1 (multimode) for 3900 ISR G2
SM-1-STM1-MM-C=	Channelized STM-1 (multimode) for 3900 ISR G2
SM-1-STM1-SM-C	Channelized STM-1 (singlemode) for 3900 ISR G2
SM-1-STM1-SM-C=	Channelized STM-1 (singlemode) for 3900 ISR G2

Table 1. Product Part Numbers Affected by This Announcement

For More Information

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod end of life.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: <u>http://www.cisco.com/web/feeds/products/end_of_life_rss.xml</u>.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA