

## End-of-Sale and End-of-Life Announcement for the Cisco 16-Port EtherSwitch Prestandard Power over Ethernet Network Modules

## EOL6395

Cisco<sup>®</sup> announces the end-of-sale and end-of life dates for the Cisco 16-Port EtherSwitch Prestandard Power over Ethernet Network Modules. The last day to order the affected product(s) is October 6, 2008. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	April 7, 2008
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 6, 2008
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 4, 2009
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	October 6, 2009
End of New Service Attachment Date: HW	· · · · · · · · · · · · · · · · · · ·	
End of Service Contract Renewal Date: HW	· · · · · · · · · · · · · · · · · · ·	
Last Date of Support: HW	ast Date of Support: HW The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	

 
 Table 1.
 End-of-Life Milestones and Dates for the Cisco 16-Port EtherSwitch Prestandard Power over Ethernet Network Modules

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2.	Product Part Numbers A	Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
NM-16ESW-PWR	1 16 port 10/100 EtherSwitch NM with prestandard POE	NME-16ES-1G-P	EtherSwitch Service Mod 16 10/100T POE + 1 GE, IP Base
NM-16ESW-PWR-1GIG	1 16 port 10/100 EtherSwitch NM with prestandard POE + GE	NME-16ES-1G-P	EtherSwitch Service Mod 16 10/100T POE + 1 GE, IP Base
NM-16ESW-PWR-1GIG=	1 16 port 10/100 EtherSwitch NM with prestandard POE + GE	NME-16ES-1G-P=	EtherSwitch Service Mod 16 10/100T POE + 1 GE, IP Base
NM-16ESW-PWR=	1 16 port 10/100 EtherSwitch NM with prestandard POE	NME-16ES-1G-P=	EtherSwitch Service Mod 16 10/100T POE + 1 GE, IP Base

## **Product Migration Options**

Customers are encouraged to migrate to the Cisco 16-port EtherSwitch Service Module with standards-based Power over Ethernet (product number NME-16ES-1G-P). Information about this product can be found at:

http://www.cisco.com/en/US/prod/collateral/routers/ps5855/product\_data\_sheet0900aecd8028d15f \_ps5854\_Products\_Data\_Sheet.html. The newer EtherSwitch service module greatly expands the capabilities of the previous service modules by providing support for new features such as IEEE 802.3a/f Power over Ethernet, local Layer 3 switching, advanced quality of service, Cisco Network Assistant and Cisco Emergency Responder, to name a few, as well as feature parity with Cisco Catalyst 3560 Series Switches. Additionally, the newer EtherSwitch service module can take full advantage of the increased performance capabilities and new form factors of the enhanced network module slot on Cisco Integrated Services Routers.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <u>http://www.cisco.com/go/tradein/</u>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the Cisco 16-Port EtherSwitch Prestandard Power over Ethernet Network Modules through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <u>http://www.cisco.com/go/eos</u>

## For More Information

For more information about the Cisco 16-port EtherSwitch Service Modules with standards-based Power over Ethernet, visit

http://www.cisco.com/en/US/prod/collateral/routers/ps5855/product\_data\_sheet0900aecd8028d15f \_ps5854\_Products\_Data\_Sheet.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod\_end\_of\_life.html

To subscribe to receive end-of-life/end-of-sale information, go to:

http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice



Americas Headquarters Ciseo Systems, Inc. San Jose, CA Asia Pacific Headquartera Gisco Systems (USA) Pia Lid. Singapore Europe Headquarters Cisco Systems Informational BV Amsterdam, The Notherlands

Clace has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CODE, CODET, Class Ess. Class StudiumVision, the Class loga, DOE, and Welcome to the Human Network are trademarks: Changing the Way We Work, Live, Play, and Learn is a service more and Access Fagistrar, Almost, Asyncols, Bringing the Meating To You, Catalyst, CODA, CODE, COLE, COLE, CONA, CODE, COVE, Close, the Class Cartinad Internetwork Expert logo, Close Dist, Class Systems, Class Systems,

All other tradements mentioned in this document or Website are the property of their respective owners. The use of the word partner dose not imply a partner while between Cleco and any other company (08034)

Printed in USA

C51-466098-00 04/08