

## End-of-Sale and End-of-Life Announcement for the Cisco 2600/2800/3600/3700/3800 Series 16-Port Asynchronous Module

EOL6685

Cisco<sup>®</sup> announces the end-of-sale and end-of life dates for the Cisco 2600/2800/3600/3700/3800 Series 16-Port Asynchronous Module. The last day to order the affected product(s) is September 14, 2009. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Cisco 2600/2800/3600/3700/3800 Series 16-Port Asynchronous Module

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	March 16, 2009
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 14, 2009
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	September 14, 2010
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	September 14, 2010
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and- support contract, this is the last date to order a new service-and- support contract or add the equipment and/or software to an existing service-and-support contract.	
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	December 10, 2013
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	September 13, 2014

HW = Hardware, OS SW = Operating System Software, App. SW = Application Software

 Table 2.
 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
NM-16A	16 port Asynchronous Module	HWIC-16A	16-Port Async HWIC
NM-16A=	16 port Asynchronous Module	HWIC-16A=	16-Port Async HWIC

## **Product Migration Options**

Customers are encouraged to migrate to the Cisco 1800/2800/3800 Series 16-Port Asynchronous High-Speed WAN Interface Card. Additional information about this product and other Cisco asynchronous high-speed WAN interface cards can be found at:

http://www.cisco.com/en/US/prod/collateral/modules/ps5949/ps6182/product\_data\_sheet0900aecd\_80274416.html

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <a href="http://www.cisco.com/go/tradein/">http://www.cisco.com/go/tradein/</a>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the Cisco 2600/2800/3600/3700/3800 Series 16-Port Asynchronous Module through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <a href="http://www.cisco.com/go/eos">http://www.cisco.com/go/eos</a>

Service prices for Cisco products are subject to change after the product End of Sale date.

## For More Information

For more information about the Cisco 1800/2800/3800 Series 16-Port Asynchronous High-Speed WAN Interface Card, visit

http://www.cisco.com/en/US/prod/collateral/modules/ps5949/ps6182/product\_data\_sheet0900aecd 80274416.html, or contact your local account representative.

To request information about the Cisco 1800/2800/3800 Series 16-Port Asynchronous High-Speed WAN Interface Card, send an e-mail to <a href="mailto:cs-3800@cisco.com">cs-3800@cisco.com</a>.

For more information about the Cisco End-of-Life Policy, go to: <a href="http://www.cisco.com/en/US/products/prod">http://www.cisco.com/en/US/products/prod end of life.html</a>

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice



Americas Headquartere Cisco Systems, Inc. San Jose, CA Asia Pacific Headquartera Cisco Systoms (USA) Pio Ltd. Singacore Europe Headquarters Circo Systema International RV Arnsterdam, The Netherlands

Clace has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Clace Website at www.cisco.com/go/offices.

CODE, CODE, Class East Class Health Presence, the Class Clas

All other trademarks mentioned in this document or website are the property of their respective eremere. This use of the word permer does not imply a permerable relationship between Cisco and any other company, (9812H).

Printed in USA C51-521084-00 02/09