# ılıılı cısco

# End-of-Sale and End-of-Life Announcement for the Cisco SPS208G-G5 8-Port 10/100 + 2-Port Gigabit SP Switch

#### EOL8793

Cisco announces the end-of-sale and end-of-life dates for the Cisco SPS208G-G5 8-Port 10/100 + 2-Port Gigabit SP Switch. The last day to order the affected product(s) is December 18, 2012. Customers will continue to receive phone support from the Cisco Small Business Support Center (SBSC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active product warranties, support will be available as stated in the product warranty terms and conditions, even if this date exceeds the Last Date of Support shown in Table 1.

| Milestone                           | Definition   | Date               |
|-------------------------------------|--|--------------------|
| End-of-Life<br>Announcement Date    | The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.  | September 18, 2012 |
| End-of-Sale Date                    | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.  | December 18, 2012  |
| End of Phone Support<br>Date:<br>HW | The last date to receive phone support as part of the product warranty. After this date,<br>all phone support services for the product are available with additional charges or<br>support fees. In some cases, support may not be available.  | December 18, 2013  |
| Last Ship Date:<br>HW               | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.  | March 18, 2013     |
| Last Date of Support:<br>HW         | Date of Support: The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details. |                    |

#### Table 1. End-of-Life Milestones and Dates for the Cisco SPS208G-G5 8-Port 10/100 + 2-Port Gigabit SP Switch

HW = Hardware OS SW = Operating System Software App. SW = Application Software

| End-of-Sale Product<br>Part Number | Product Description                         | Replacement Product<br>Part Number | Replacement Product<br>Description                                | Additional Information |
|------------------------------------|---|------------------------------------|---|------------------------|
| SPS208G                            | 8-port 10/100 + 2-Port<br>Gigabit SP Switch | SRW208G-K9-NA                      | SF 302-08 8-port 10/100<br>Managed Switch with<br>Gigabit Uplinks | -                      |
| SPS208G-G5                         | 8-port 10/100 + 2-Port<br>Gigabit SP Switch | SRW208G-K9-G5                      | SF 302-08 8-port 10/100<br>Managed Switch with<br>Gigabit Uplinks | -                      |

# **Product Migration Options**

Customers are encouraged to migrate to the Cisco SF302-08 8-Port 10/100 Managed Switch with Gigabit Uplinks (SRW208G-K9-G5). Information about this product can be found at:

http://www.cisco.com/cisco/web/solutions/small\_business/products/routers\_switches/300\_series\_switches/index.ht ml.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about\_cisco\_takeback\_recycling.html.

### For More Information

For more information about the Cisco SF302-08 8-Port 10/100 Managed Switch with Gigabit Uplinks, visit <u>http://www.cisco.com/cisco/web/solutions/small\_business/products/routers\_switches/300\_series\_switches/index.ht</u> <u>ml</u>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: <u>http://www.cisco.com/en/US/products/products\_end-of-life\_policy.html</u>.

<sup>\*\*</sup> For more information about the Cisco Product Warranties, go to: <u>http://www.cisco.com/en/US/products/prod\_warranties\_listing.html</u>.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html.

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: <u>http://www.cisco.com/web/feeds/products/end\_of\_life\_rss.xml</u>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA