



Price Increase for Cisco Catalyst 2960G 24-Port and 48-Port Switches

PB705278

Cisco is announcing a price increase for the Cisco[®] Catalyst[®] 2960G 24-port and 48-port switch product lines, effective April 7, 2012. This price increase follows the end-of-sale announcement

(http://www.cisco.com/en/US/prod/collateral/switches/ps5718/ps6406/end_of_life_c51-674040.html) of the Cisco 2960G switches on August 1, 2011.

Table 1 lists the product part numbers and the new base price effective April 7, 2012.

Table 1. Updated Pricing Information

Product Part Number	Product Description	Base Price (Current)	Base Price (Effective April 7, 2012)
WS-C2960G-24TC-L	Cisco Catalyst 2960 24 10/100/1000, 4 T/Small Form-Factor Pluggable (SFP) LAN Base image	\$3,295	\$3,795
WS-C2960G-48TC-L	Cisco Catalyst 2960 48 10/100/1000, 4 T/SFP LAN Base image	\$5,995	\$6,895

Product Migration Options

All customers are encouraged to migrate to the Cisco Catalyst 2960S product family. These replacement or migration switches are equivalent to or better than the end-of-sale products and are priced lower as well. Table 2 provides direct replacement SKUs for the end-of-sale Cisco Catalyst 2960G products.

Table 2. Replacement Product Information

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
WS-C2960G-24TC-L	Cisco Catalyst 2960 24 10/100/1000, 4 T/SFP LAN Base image	WS-C2960S-24TS-L	Cisco Catalyst 2960S 24 Gigabit Ethernet (GE), 4 x SFP LAN Base
WS-C2960G-48TC-L	Cisco Catalyst 2960 48 10/100/1000, 4 T/SFP LAN Base image	WS-C2960S-48TS-L	Cisco Catalyst 2960S 48 GE, 4 x SFP LAN Base

In addition to the direct replacement SKUs, the Cisco Catalyst 2960S series provides a full portfolio of 24/48 data and Power over Ethernet Plus (PoE+) switches, as shown in Table 3.

Table 3. Cisco Catalyst 2960S Product Portfolio

Switch Model	Description	Uplinks
Cisco Catalyst 2960S Switches with 10 GE Uplinks and 10/100/1000 Ethernet Connectivity (LAN Base Software)		
Cisco Catalyst 2960S-48FPD-L	48 Ethernet 10/100/1000 PoE+ ports	2 10 GE SFP+ or 2 GE SFP ports
Cisco Catalyst 2960S-48LPD-L	48 Ethernet 10/100/1000 PoE+ ports	2 10 GE SFP+ or 2 GE SFP ports
Cisco Catalyst 2960S-24PD-L	48 Ethernet 10/100/1000 PoE+ ports	2 10 GE SFP+ or 2 GE SFP ports
Cisco Catalyst 2960S-48TD-L	48 Ethernet 10/100/1000 ports	2 10 GE SFP+ or 2 GE SFP ports
Cisco Catalyst 2960S-24TD-L	24 Ethernet 10/100/1000 ports	2 10 GE SFP+ or 2 GE SFP ports
Cisco Catalyst 2960S Switches with GE Uplinks and 10/100/1000 Ethernet Connectivity (LAN Base Software)		
Cisco Catalyst 2960S-48FPS-L	48 Ethernet 10/100/1000 PoE+ ports	4 GE SFP ports
Cisco Catalyst 2960S-48LPS-L	48 Ethernet 10/100/1000 PoE+ ports	4 GE SFP ports
Cisco Catalyst 2960S-24PS-L	24 Ethernet 10/100/1000 PoE+ ports	4 GE SFP ports
Cisco Catalyst 2960S-48TS-L	48 Ethernet 10/100/1000 ports	4 GE SFP ports
Cisco Catalyst 2960S-24TS-L	24 Ethernet 10/100/1000 ports	4 GE SFP ports
Cisco Catalyst 2960S Switches with GE Uplinks and 10/100/1000 Ethernet Connectivity (LAN Lite Software)		
Cisco Catalyst 2960S-48TS-S	48 Ethernet 10/100/1000	2 GE SFP ports
Cisco Catalyst 2960S-24TS-S	24 Ethernet 10/100/1000	2 GE SFP ports

For More Information

For more information about the Cisco Catalyst 2960S 24-port and 48-port switches, go to <http://www.cisco.com/en/US/products/ps12200/index.html>, or contact your local account representative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)