



End-of-Sale and End-of-Life Announcement for the Cisco DOCSIS 2.0 Residential Gateways with Digital Voice

EOL8021

Cisco announces the end-of-sale and end-of-life dates for the Cisco DOCSIS 2.0 Residential Gateways with Digital Voice. The last day to order the affected product(s) is June 8, 2012. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco DOCSIS 2.0 Residential Gateways with Digital Voice

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	December 9, 2011
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 8, 2012
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 6, 2012
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	June 8, 2013
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	June 8, 2013
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	September 3, 2016
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete **. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	June 30, 2017

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4013345	DPC2434 GW, 802.11g, 2pt EMTA, 4pt ENET, Int PS, Btry, NA(Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		
4014308	DPC2434X GW, 802.11g, 2pt EMTA, EUR LPS (Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		
4021375	Pwr Kit, 125V NEMA 5-15, 8CH Bal AES Aud, 2:16 Exp Rack, NA	See the Product Migration Options section below for detailed information on replacing this product.		
4027662	DPQ2425-2200 GW, DOCSIS 2.0, 2pt, Int PS, Btry, NA(Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		
4028605	EPC2425 GW, EMTA, 12V EU Sw PS, No Bat, w/USB, UPC Only (Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		
4028611	DPC2434 GW, DOCSIS 2.0, Wrls EMTA, NA 15V LPS, 802.11g (Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		
4028618	DPC2434 GW, Wrls EMTA, No Btry Cap, UPS, No P/C (Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		
4028933	DPC2434x GW, Wrls EMTA, 2pt, 15V ARG Sw LPS (Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		
4030556	EPC2425 GW, DOCSIS 2.0, EMTA, 12V UK SW LPS (Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		
4030557	EPC2425 GW, 4pt ENET, 12V EU Wall-mt Sw PS, UPC (Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		
4036003	DPC2425 GW, DOCSIS 3.0, 15V LPS, No USB/Btry, TW/BH (Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		
4036004	DPQ2425-2200 GW, DOCSIS 3.0, No USB, Btry, TW/BH Only (Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		
4036005	DPQ2425 GW, DOCSIS 3.0, No USB/Btry, TW/BH Only (Mult=10)	See the Product Migration Options section below for detailed information on replacing this product.		

Product Migration Options

Customers are encouraged to contact an account manager or distributor for migration information. More information about residential gateways with digital voice can be found at:

<http://www.cisco.com/en/US/products/ps11703/index.html>.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco DOCSIS 2.0 Residential Gateways with Digital Voice through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco Residential Gateways with Digital Voice, visit <http://www.cisco.com/en/US/products/ps11703/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

** For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)