

End-of-Sale and End-of-Life Announcement for the Cisco Transponders for Model GS7000 and Model 6940 GainMaker Amplifiers and Nodes

EOL9190

Cisco announces the end-of-sale and end-of-life dates for the Cisco Transponders for Model GS7000 and Model 6940 GainMaker Amplifiers and Nodes. The last day to order the affected product(s) is December 30, 2013. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Cisco Transponders for Model GS7000 and Model 6940 GainMaker Amplifiers and Nodes

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	July 1, 2013
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 30, 2013
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 30, 2014
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	December 30, 2014
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 30, 2014
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	March 27, 2018
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 31, 2018

HW = Hardware OS SW = Operating System Software App. SW = Application Software

 Table 2.
 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
345G631210000000	GM-RS HGBT, 65/86, Xpdr, TC	There is currently no replacement product available for this product.		
345G631211117A01	GM-RS HGBT, 65/86, Xpdr, TC, PS, Ctd Hsg, SA, 1310FP, Rx	There is currently no replacement product available for this product.		
345G631211117B01	GM-RS HGBT, 65/86, Xpdr, TC, PS, Ctd Hsg, SA, 1310DFB, Rx	There is currently no replacement product available for this product.		
346G233211117O01	GMN-RS 42/54 1G HO HGBT-T SCA X1CWDM HMS	There is currently no replacement product available for this product.		
346G233211117P01	GM-RS HGBT(HO), 42/54, HMS Xpdr, CB, TC, PS, CtdHsg, SA, CWDM1550, Rx	There is currently no replacement product available for this product.		
346G233211117Q01	GM-RS HGBT(HO), 42/54, HMS Xpdr, CB, TC, Ctd Hsg, SA, CWDM1530nm, Rx	There is currently no replacement product available for this product.		
346G233211117R01	GM-RS HGBT(HO), 42/54, HMS Xpdr, CB, TC, PS, CtdHsg, SA, CWDM1510, Rx	There is currently no replacement product available for this product.		
346G631210000000	GM-RS HGBT(HO), 65/86, Xpdr, TC	There is currently no replacement product available for this product.		
346G631211117A01	GM-RS HGBT(HO), 65/86, Xpdr, TC, PS, Ctd Hsg, SA, 1310FP, Rx	There is currently no replacement product available for this product.		
346G631211117B01	GM-RS HGBT(HO), 65/86, Xpdr, TC, PS, Ctd Hsg, SA, 1310DFB, Rx	There is currently no replacement product available for this product.		
346G641210000000	GM-RS HGBT(HO), 65/86, Xpdr/Seg, TC	There is currently no replacement product available for this product.		
346G641211117B01	GM-RS HGBT(HO), 65/86, Xpdr/Seg, TC, PS, Ctd Hsg, SA, 1310DFB, Rx	There is currently no replacement product available for this product.		
4006432	GM Node Xpdr, HMS	4039677	GM Node, Std, DOCSIS/EuroDOCSIS Transponder Kit	
4027963	GM Node, 4-Port, HMS Transponder Kit	4039676	ASSY, DOCSIS XPDR W/PKG, GM NODE	
447G233211117AX1	GM-RS, 4-Pt (HO), 42/54, Xpdr, CB, PS, Ctd Hsg, SA, 1310FP, Rx	There is currently no replacement product available for this product.		
447G233211117BX1	GM-RS, 4-Pt (HO), 42/54, HMS, CB, PS, Ctd Hsg, SA, 1310DFB, Rx	There is currently no replacement product available for this product.		
447G233211117OX1	GM-RS, 4-Pt (HO), 42/54, HMS Xpdr, CB, PS, Ctd Hsg, SA, CWDM1570, Rx	There is currently no replacement product available for this product.		
447G233211117QX1	GM-RS, 4-Pt (HO), 42/54, HMS Xpdr, CB, PS, Ctd Hsg, SA, CWDM1530, Rx	There is currently no replacement product available for this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
447G233211117RX1	GM-RS, 4-Pt (HO), 42/54, HMS Xpdr, CB, PS, Ctd Hsg, SA, CWDM1510, Rx	There is currently no replacement product available for this product.		
447G233211127TO1	GM-RS, 4-Pt (HO), 42/54, HMS, CB, PS, CtdHsg, SP, CWDM1470/1570, RX	There is currently no replacement product available for this product.		
447G233211127TX1	GM-RS, 4-Pt (HO), 42/54, HMS, CB, PS, Ctd Hsg, SP, CWDM1470, Rx	There is currently no replacement product available for this product.		
447G243211117BB1	GM-RS, 4-Pt(HO), 42/54, CB, TC, PS, Ctd Hsg, SA, 2/DFB1310, Rx	There is currently no replacement product available for this product.		
447G243211117OQ1	GM-RS, 4-Pt (HO), 42/54, HMS, CB, TC, PS, Ctd Hsg, SA, CWDM1570/30, Rx	There is currently no replacement product available for this product.		
447G243211118B01	GM-RS, 4-Pt(HO), 42/54, CB, TC, PS, Ctd Hsg, SA, 2:1 bdr, DFB1310, Rx	There is currently no replacement product available for this product.		
447G243211118BX1	GM-RS, 4-Pt(HO), 42/54, CB, TC, PS, Ctd Hsg, SA, 2:1 bdr, DFB1310, Rx	There is currently no replacement product available for this product.		
447G633211115AX1	GM-RS, 4-Pt(HO), 65/86, Xpdr, CB, TC, PS, Ctd Hsg, SA, DWDM, ITU20, Rx	There is currently no replacement product available for this product.		
447G633211115BX1	GM-RS, 4-Pt (HO), 65/86, Xpdr, CB, TC, PS, Ctd Hsg, SA, 1310DFB, Rx	There is currently no replacement product available for this product.		
447G633211115CX1	GM-RS, 4-Pt (HO), 65/86, Xpdr, CB, TC, PS, Ctd Hsg, SA, DWDM, ITU22, Rx	There is currently no replacement product available for this product.		
447G633211115DX1	GM-RS, 4-Pt (HO), 65/86, Xpdr, CB, TC, PS, Ctd Hsg, SA, DWDM, ITU23, Rx	There is currently no replacement product available for this product.		
447G633211115EX1	GM-RS, 4-Pt(HO), 65/86, Xpdr, CB, TC, PS, Ctd Hsg, SA, DWDM, ITU24, Rx	There is currently no replacement product available for this product.		
447G633211115FX1	GM-RS, 4-Pt(HO), 65/86, Xpdr, CB, TC, PS, Ctd Hsg, SA, DWDM, ITU25, Rx	There is currently no replacement product available for this product.		
447G633211115GX1	GM-RS, 4-Pt(HO), 65/86, Xpdr, CB, TC, PS, Ctd Hsg, SA, DWDM, ITU26, Rx	There is currently no replacement product available for this product.		
447G633211115HX1	GM-RS, 4-Pt (HO), 65/86, Xpdr, CB, TC, PS, Ctd Hsg, SA, DWDM, ITU27, Rx	There is currently no replacement product available for this product.		
715980	GM Amp Xpdr, Agile 5- 65/45-174MHz	4039677	GM Node, Std, DOCSIS/EuroDOCSIS Transponder Kit	
744234	GM Node Xpdr, Agile 5- 65/45-174MHz	4039677	GM Node, Std, DOCSIS/EuroDOCSIS Transponder Kit	

Product Migration Options

Customers are encouraged to migrate to the Cisco DOCSIS/EuroDOCSIS Transponders. Information about this product can be found at: http://www.cisco.com/en/US/products/ps9066/products data sheets list.html.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about

Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Transponders for Model GS7000 and Model 6940 GainMaker Amplifiers and Nodes through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: http://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco DOCSIS/EuroDOCSIS Transponders, visit http://www.cisco.com/en/US/products/ps9066/products data sheets list.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod warranties listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

http://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end of life rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

 $Cisco\ has\ more\ than\ 200\ offices\ worldwide.\ Addresses,\ phone\ numbers,\ and\ fax\ numbers\ are\ listed\ on\ the\ Cisco\ Website\ at\ www.cisco.com/go/offices.$

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-728844-00 07/13