

End-of-Sale and End-of-Life Announcement for the D9032 MPEG-2 Encoder

EOL7668

Cisco announces the end-of-sale and end-of-life dates for the D9032 MPEG-2 Encoder. The last day to order the affected product(s) is December 6, 2011. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions, even if this date exceeds the Last Date of Support shown in Table 1.

| Milestone | Definition | Date |
|--|---|------------------|
| End-of-Life Announcement Date | The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public. | June 7, 2011 |
| End-of-Sale Date | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | December 6, 2011 |
| Last Ship Date: HW | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | March 5, 2012 |
| End of SW Maintenance Releases Date: HW | The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software. | December 5, 2012 |
| End of Routine Failure Analysis Date: HW | The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect. | December 5, 2012 |
| End of New Service Attachment Date: HW | | |
| End of Service Contract Renewal Date: HW | The last date to extend or renew a service contract for the product. | March 2, 2016 |
| Last Date of Support: HW | | |

| Table 4 | End of Life Milestence and Dates for the D0020 MDEC 2 Enceder |
|----------|---|
| Table 1. | End-of-Life Milestones and Dates for the D9032 MPEG-2 Encoder |

HW = Hardware

Table 2. Product Part Numbers Affected by This Announcement

OS SW = Operating System Software

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|------------------------------------|------------------------------|--|------------------------------------|------------------------|
| 4008824011 | D9032 PAL/NTSC/SDI 2ST AC | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 4009407 | D9032 DC PSU (instead of AC) | See the Product Migration Options section below for detailed information on replacing this product. | | |

App. SW = Application Software

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|------------------------------------|---|--|------------------------------------|------------------------|
| 4009980 | D9032 Kit,DC PSU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 4012334 | D9032 to D9034-S Upgrade (AVC Encoding) | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 4013873.302.060.AC | D9032 Encoder,AVIB,AC,Verizon | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 4013873.302.061.AA | D9032 AVIB For Verizon AC | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387300000 | D9032,PAL/NTSC,4:2:0 SD Encoder,AC,2ST PT/LII,ASI/IP,No P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387300201 | D9032,SDI/CS,4:2:0,AC,2S T PT/LII,CC,ASI/IP Out,VBI,No P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387301000 | D9032,PAL/NTSC,4:2:0 SD Encoder,AC,4ST PT/LII,ASI/IP,No P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387301100 | D9032,CS,4:2:0,AC,4ST PT/LII Audio,CC,ASI/IP Out,No/P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387301201 | D9032,SDI/CS,4:2:0,AC,4S T PT/LII,CC,ASI/IP Out,VBI,No P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387301252 | D9032,SDI/CS,AC,4ST,VBI, 2/AC-3,NR,4:2:2,IP SM,DPI,Auto-cat | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387310000 | D9032,DC,2ST,ASI/IP Out | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387310026 | D9032,DC,2ST,AC-3,NR | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387310126 | D9032,CS,DC,2ST,AC- 3,NR | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387310201 | D9032,SDI/CS,DC,2ST,VBI | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387310206 | D9032,SDI/CS,DC,2ST, VBI,AC-3,NR | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387310250 | D9032,SDI/CS,4:2:0,DC,2S T PT/LII Audio,CC,ASI/IP Out,VBI,DPI | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|------------------------------------|--|--|------------------------------------|------------------------|
| 401387311203 | D9032,SDI/CS,DC,4ST, VBI,SM | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387311208 | D9032,SDI/CS,DC,4ST, VBI,NR,SM | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387311220 | D9032,SDI/CS,DC,4ST, VBI,AC-3,NR,4:2:2,SM,DPI | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387311221 | D9032,SDI/CS,DC,4ST, VBI,2/AC3,NR,4:2:2,SM,DPI | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320000 | D9032,4:2:0,AC,2ST PT/LII,CC,ASI/IP Out,EU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320022 | D9032,PAL/NTSC,4:2:0, AC,2ST PT/LII Aud,ASI/IP Out,NR,EU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320028 | D9032,PAL/NTSC,4:2:0, AC,2ST PT/LII Audio,NR,Statmux,EU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320035 | D9032,PAL.NTSC,4:2:0, AC,2ST PT/LII Audio,DPI,EU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320100 | D9032,CS,AC,2ST,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320122 | D9032,CS,AC,2ST,NR,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320126 | D9032 PAL/NTSC CLSGHT AC EU 2ST T26 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320128 | D9032,CS,AC,2ST,NR,SM, EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320136 | D9032,CS,AC,2ST,4:2:2, EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320201 | D9032,SDI/CS,AC,2ST, VBI,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320202 | D9032,SDI/CS,AC,2ST, VBI,NR,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320203 | D9032,SDI/CS,AC,2ST, VBI,SM,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|------------------------------------|--|--|------------------------------------|------------------------|
| 401387320204 | D9032,SDI/CS,AC,2ST, VBI,AC-3,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320206 | D9032,SDI/CS,AC,2ST, VBI,AC-3,NR,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320208 | D9032,SDI/CS,AC,2ST, VBI,NR,SM,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320209 | D9032,SDI/CS,AC,2ST, VBI,4:2:2,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320210 | D9032,SDI/CS,4:2:2,AC,2S T PT/LII,CC,ASI/IP Out,VBI,NR,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320211 | D9032,SDI/CS,AC,2ST, VBI,4:2:2,SM,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320218 | D9032,SDI/CS,AC,2ST, VBI,NR,SM,Auto-cat,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320239 | D9032,SDI/CS,AC,2ST, VBI,NR,DPI,Auto-cat,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320243 | D9032,SDI/CS,AC,2ST, VBI,AC-3,4:2:2,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320244 | D9032,SDI/CS,AC,2ST, VBI,AC-3,NR,SM,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320245 | D9032,SDI/CS,AC,2ST, VBI,IP SM,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320247 | D9032,SDI/CS,AC,2ST, VBI,SM,DPI,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320248 | D9032,SDI/CS,AC,2ST, VBI,NR,IP SM,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320250 | D9032,SDI/CS,AC,2ST, VBI,IP SM,Auto-cat,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387320265 | D9032,SDI/CS,4:2:0,AC,2S T PT/LII,VBI,AC3 Ch1- 2,SM,DPI,EU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321000 | D9032,AC,4ST,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|------------------------------------|--|--|------------------------------------|------------------------|
| 401387321022 | D9032 PAL/NTSC AC EU 4ST T22 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321100 | D9032,CS,AC,4ST,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321201 | D9032,SDI/CS,AC,4ST, VBI,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321202 | D9032,SDI/CS,4:2:0,AC,4S T PT/LII Audio,VBI,NR,EU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321203 | D9032,SDI/CS,AC,4ST, VBI,SM,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321204 | D9032,SDI/CS,4:2:0,AC,4S T PT/LII,ASI/IP Out,VBI,AC3,EU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321206 | D9032,SDI/CS,4:2:0,AC,4S T PT/LII Audio,VBI,AC3,NR,EU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321208 | D9032,SDI/CS,AC,4ST, VBI,NR,SM,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321209 | D9032,SDI/CS,AC,4ST, VBI,4:2:2,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321210 | D9032 PAL/NTSC CLSGHT/SDI AC EU 4ST T10 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321212 | D9032,SDI/CS,AC,4ST, VBI,NR,DPI,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321233 | D9032,SDI/CS,AC,4ST, VBI,2/AC-3,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321238 | D9032,SDI/CS,AC,4ST, VBI,2/AC-3,NR,4:2:2,Auto- cat,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321240 | D9032,SDI/CS,AC,4ST, VBI,2/AC- 3,NR,4:2:2,SM,DPI,Auto- cat,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321245 | D9032,SDI/CS,AC,4ST, VBI,IP SM,EU | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321248 | D9032,SDI/CS,4:2:0,AC,4S T PT/LII Audio,VBI,NR,IP SM,EU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|------------------------------------|--|--|------------------------------------|------------------------|
| 401387321254 | D9032,SDI/CS,4:2:0,AC,4S T PT/LII,VBI,NR,4:2:2,IP SM,EU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387321261 | D9032,SDI/CS,4:2:0,AC,4S T PT/LII,ASI/IP Out,VBI,DPI,EU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330000 | D9032,AC,2ST,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330026 | D9032,AC,2ST,AC- 3,NR,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330028 | D9032,PAL/NTSC,4:2:0, AC,2ST PT/LII Audio,NR,SM,US P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330035 | D9032,AC,2ST,DPI,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330058 | D9032,PAL/NTSC,4:2:0, AC,2ST PT/LII,AC3 Ch1- 2,NR,IP SM,US P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330100 | D9032,CS,AC,2ST,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330124 | D9032,CS,AC,2ST, AC-3,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330126 | D9032,CS,AC,2ST, AC-3,NR,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330131 | D9032,CS,AC,2ST, AC-3,NR,SM,DPI,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330201 | D9032,SDI/CS,AC,2ST, VBI,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330202 | D9032,SDI/CS,AC,2ST, VBI,NR,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330203 | D9032,SDI/CS,AC,2ST, VBI,SM,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330204 | D9032,SDI/CS,AC,2ST, VBI,AC-3,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330206 | D9032,SDI/CS,AC,2ST, VBI,AC-3,NR,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|------------------------------------|--|--|------------------------------------|------------------------|
| 401387330208 | D9032,SDI/CS,AC,2ST, VBI,NR,SM,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330209 | D9032,SDI/CS,AC,2ST, VBI,4:2:2,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330212 | D9032,SDI/CS,AC,2ST, VBI,NR,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330213 | D9032,SDI/CS,AC,2ST, VBI,AC-3,NR,4:2:2,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330216 | D9032,SDI/CS,AC,2ST, VBI,NR,Auto-cat,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330217 | D9032 PAL/NTSC CLSGHT/SDI AC US 2ST | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330248 | D9032,SDI/CS,AC,2ST, VBI,NR,IP SM,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387330253 | D9032,SDI/CS,4:2:0,AC,2S T PT/LII,VBI,AC3 Ch1- 2,NR,DPI,US P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387331000 | D9032,AC,4ST,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387331029 | D9032,AC,4ST, AC-3,NR,SM,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387331100 | D9032 PAL/NTSC CLSGHT AC US 4ST T00 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387331201 | D9032,SDI/CS,AC,4ST, VBI,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387331209 | D9032,SDI/CS,AC,4ST, VBI,4:2:2,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387331210 | D9032 PAL/NTSC CLSGHT/SDI AC NA 4ST | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387331216 | D9032,SDI/CS,AC,4ST, VBI,NR,Auto-cat,NA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387331230 | D9032,SDI/CS,4:2:0,AC,4S T PT/LII,VBI,AC3 Ch 1/2,NR,SM,US P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|------------------------------------|--|--|------------------------------------|------------------------|
| 401387331251 | D9032,SDI,4:2:0,AC,4ST PT/LII,VBI,AC3 Ch1- 4,NR,DPI,US P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387331263 | D9032,SDI/CS,4:2:0,AC,4S T,VBI,AC-3,NR,IP Statmux,NA P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387340100 | D9032 PAL/NTSC CLSGHT AC UK 2ST T00 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387340201 | D9032,SDI/CS,4:2:0,2ST PT/LII Audio,CC,ASI/IP Out,VBI,UK P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387340202 | D9032 PAL/NTSC CLSGHT/SDI AC UK 2ST T02 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387340208 | D9032 PAL/NTSC CLSGHT/SDI AC UK 2ST T08 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387340209 | D9032 PAL/NTSC CLSGHT/SDI AC UK 2ST T09 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387340210 | D9032 PAL/NTSC CLSGHT/SDI AC UK 2ST T10 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387340248 | D9032,SDI/CS,4:2:0,AC,2S T PT/LII,CC,ASI/IP Out,VBI,NR,UK P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387341202 | D9032,SDI/CS,AC,4ST, VBI,NR,UK | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387341208 | D9032,SDI/CS,4:2:0,AC,4S T PT/LII Audio,CC,VBI,NR,SM,UK P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387341248 | D9032,SDI/CS,4:2:0,AC,4S T PT/LII,VBI,NR,IP Based SM,UK P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387341263 | D9032,SDI/CS,4:2:0,AC,4S T PT/LII Audio,AC3,NR,IP Stat Mux,UK | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387350000 | D9032,AC,2ST,AUS | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387350022 | D9032,AC,2ST,NR,AUS | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387350100 | D9032,CS,AC,2ST,AUS | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|------------------------------------|---|--|------------------------------------|------------------------|
| 401387350201 | D9032,SDI/CS,AC,2ST, VBI,AUS | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387350209 | D9032,SDI/CS,4:2:0,AC,2S T PT/LII,ASI/IP Out,VBI,4:2:2,AU P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387350211 | D9032,SDI/CS,AC,2ST, VBI,4:2:2,SM,AUS | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387350245 | D9032,SDI/CS,AC,2ST, VBI,SM,AUS | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387350248 | D9032,SDI/CS,AC,2ST, VBI,NR,IP SM,AUS | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387351100 | D9032,CS,AC,4ST,AUS | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 401387351201 | D9032,CS,4:2:0,AC,4ST PT/LII Audio,CC,ASI/IP Out,VBI,AUS P/C | See the Product Migration Options section below for detailed information on replacing this product. | | |

Product Migration Options

Customers are encouraged to migrate to the Cisco Modular Encoding Platform D9036. Information about this product can be found at: <u>http://www.cisco.com/en/US/products/ps9178/products_data_sheets_list.html</u>. The D9032 encoder and D9036 encoding platform can coexist in the same system; however, these models cannot be used together in setting up backup encoders or statmux pools.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at <u>http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html</u>.

Customers may be able to continue to purchase the D9032 MPEG-2 Encoder through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <u>http://www.cisco.com/go/eos</u>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco Modular Encoding Platform D9036, visit <u>http://www.cisco.com/en/US/products/ps9178/products_data_sheets_list.html</u>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products end-of-life policy.html.

** For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)

Printed in USA