



## Change in Product Part Number Announcement for the Cisco D9858 Advanced Receiver Transcoder

EOL9073 - Amended

Cisco announces a change in product part numbers for the Cisco D9858 Advanced Receiver Transcoder. This is a product part number change only announcement. Customers will experience no change in functionality when using the new product part numbers. The new product part numbers are designed to simplify the customer ordering process. The last day to order the affected product using the current product part numbers is May 30, 2013. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until otherwise specified in the end-of-life announcement for the new product part numbers. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

**Table 1.** End-of-Life Milestones and Dates for the Cisco D9858 Advanced Receiver Transcoder

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	February 28, 2013
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 30, 2013
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 28, 2013

HW = Hardware    OS SW = Operating System Software    App. SW = Application Software

This is a product part number change only. Customers will experience no change in functionality, service, or lead time when using the new product IDs.

The new product IDs are designed to simplify the ordering process. Customers are encouraged to migrate to the Cisco D9858 Advanced Receiver Transcoder, configurable through the Cisco Commerce Workspace at <https://cisco-apps.cisco.com/cisco/psn/commerce#>.

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
402476600030000	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGoIP Out, No P/C	D9858-2CH-GEN-1RU	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030001	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGoIP Out, NA	D9858-2CH-GEN-1RU	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030002	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGoIP Out, Japan	D9858-2CH-GEN-1RU	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
402476600030004	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, AUS	D9858-2CH-GEN-1RU	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030005	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, EU	D9858-2CH-GEN-1RU	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030007	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, BR	D9858-2CH-GEN-1RU	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030009	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, India	D9858-2CH-GEN-1RU	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030013	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, ARG	D9858-2CH-GEN-1RU	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030014	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, UK	D9858-2CH-GEN-1RU	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030101	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, NA, Scripps	D9858-2CH-GEN-SCR=	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030201	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, NA, Hall	D9858-2CH-GEN-HAL=	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030301	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, NA, AETN	D9858-2CH-GEN-ANE=	2CH Advanced Receiver Transcoder 1RU with ATP-ISE	-
402476600030401	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, NA, Comcast	D9858-2CH-GEN-COM=	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030601	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, NA, Liberty Sport	D9858-2CH-GEN-LIB=	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600030701	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, NA, Altitude Sprts	D9858-2CH-GEN-ALT=	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476600150101	D9858 ART 2HD DFPT STAT GEN ISE SC NA	D9858-2CH-GEN-1RU	2CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476601030000	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, ATP ISE, No P/C	D9858-2CH-ATP-1RU	2CH Advanced Receiver Transcoder 1RU with ATP-ISE	-
402476601030001	D9858 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, ATP ISE, NA	D9858-2CH-ATP-1RU	2CH Advanced Receiver Transcoder 1RU with ATP-ISE	-
402476602010000	D9858-1 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, No P/C	D9858-1CH-GEN-1RU	1CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476602010001	D9858-1 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, NA	D9858-1CH-GEN-1RU	1CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476602010002	D9858-1 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, JPN	D9858-1CH-GEN-1RU	1CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476602010004	D9858-1 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, AUS	D9858-1CH-GEN-1RU	1CH Advanced Receiver Transcoder 1RU with GEN-ISE	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
402476602010005	D9858-1 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, EU	D9858-1CH-GEN-1RU	1CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476602010009	D9858-1 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, India	D9858-1CH-GEN-1RU	1CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476602010013	D9858-1 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, ARG	D9858-1CH-GEN-1RU	1CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476602010014	D9858-1 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, UK	D9858-1CH-GEN-1RU	1CH Advanced Receiver Transcoder 1RU with GEN-ISE	-
402476603010000	D9858-1 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, ATP ISE, No P/C	D9858-1CH-ATP-1RU	1CH Advanced Receiver Transcoder 1RU with ATP-ISE	-
402476603010001	D9858-1 Adv Rx Xcdr, ASI In, 3xASI/MPEGolP Out, ATP ISE, NA	D9858-1CH-ATP-1RU	1CH Advanced Receiver Transcoder 1RU with ATP-ISE	-

## Product Migration Options

This is a product part number change only. Customers will experience no change in functionality when using the new product IDs. The new product IDs are designed to simplify the ordering process. More information can be found at: [http://www.cisco.com/en/US/products/ps9185/products\\_data\\_sheets\\_list.html](http://www.cisco.com/en/US/products/ps9185/products_data_sheets_list.html).

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For More Information

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html).

For more information about the Cisco Product Warranties, go to:

[http://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](http://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

---

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:  
[http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml).

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.




Americas Headquarters  
Cisco Systems, Inc.  
San Jose, CA

Asia Pacific Headquarters  
Cisco Systems (USA) Pte. Ltd.  
Singapore

Europe Headquarters  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)