



## Change in Product Part Number Announcement for the Cisco PowerVu Model D9850 Program Receiver

EOL9079

Cisco announces a change in product part numbers for the Cisco PowerVu Model D9850 Program Receiver. This is a product part number change only announcement. Customers will experience no change in functionality when using the new product part numbers. The new product part numbers are designed to simplify the customer ordering process. The last day to order the affected product using the current product part numbers is May 30, 2013. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until otherwise specified in the end-of-life announcement for the new product part numbers. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

**Table 1.** End-of-Life Milestones and Dates for the Cisco PowerVu Model D9850 Program Receiver

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	February 28, 2013
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 30, 2013
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 28, 2013

HW = Hardware    OS SW = Operating System Software    App. SW = Application Software

This is a product part number change only. Customers will experience no change in functionality, service, or lead time when using the new product IDs.

The new product IDs are designed to simplify the ordering process. Customers are encouraged to migrate to the Cisco PowerVu Model D9850 Program Receiver, configurable through the Cisco Commerce Workspace at <https://cisco-apps.cisco.com/cisco/psn/commerce#>.

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4005964	D9850 Prgm Rx, SDI, AES-3id, ASI In, NA P/C	D9850-GEN-SDI-1RU	1RU with GEN-ISE & SDI	-
4005965	D9850 Prgm Rx, SDI, AES-3id, ASI In, NA P/C (NAP ISE)	D9850-NAP-SDI-1RU	1RU with NAP-ISE & SDI	-
4005966	D9850 Prgm Rx, NA P/C	D9850-GEN-ASI-1RU	1RU with GEN-ISE & ASI	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4005967	D9850 Prgm Rx, NA P/C (NAP ISE)	D9850-NAP-ASI-1RU	1RU with NAP-ISE & ASI	-
4006896	D9850 Prgm Rx, SDI, AES-3id, ASI In, EU P/C	D9850-GEN-SDI-1RU	1RU with GEN-ISE & SDI	-
4006897	D9850 Prgm Rx, SDI, AES-3id, ASI In, No P/C	D9850-GEN-SDI-1RU	1RU with GEN-ISE & SDI	-
4006898	D9850 Prgm Rx, EU P/C	D9850-GEN-ASI-1RU	1RU with GEN-ISE & ASI	-
4006899	D9850 Prgm Rx, No P/C	D9850-GEN-ASI-1RU	1RU with GEN-ISE & ASI	-
4019910	D9850 GEN 4RF ASI Out 50M Arg Pwr Cd	D9850-GEN-ASI-1RU	1RU with GEN-ISE & ASI	-
4023426	D9850 FTA 4RF ASI OUT 50MBPS	D9850-FTA-ASI-1RU	1RU with FTP-ISE & ASI	-

## Product Migration Options

This is a product part number change only. Customers will experience no change in functionality when using the new product IDs. The new product IDs are designed to simplify the ordering process.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For More Information

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html).

For more information about the Cisco Product Warranties, go to:

[http://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](http://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

[http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml).

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.




Americas Headquarters  
Cisco Systems, Inc.  
San Jose, CA

Asia Pacific Headquarters  
Cisco Systems (USA) Pte. Ltd.  
Singapore

Europe Headquarters  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)