

Change in Product Part Number Announcement for the Cisco DCM Series D9900/D9901 Digital Content Manager

EOL8046

Cisco announces a change in product part numbers for the Cisco DCM Series D9900/D9901 Digital Content Manager. This is a product part number change only announcement. Customers will experience no change in functionality when using the new product part numbers. The new product part numbers are designed to simplify the customer ordering process. The last day to order the affected product using the current product part numbers is July 29, 2011. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until otherwise specified in the end-of-life announcement for the new product part numbers. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Effective immediately, this is a product part number change only announcement as a result of the migration from the Scientific Atlanta ordering processes to the Cisco ordering process.

Table 1. End-of-Life Milestones and Dates for the Cisco DCM Series D9900/D9901 Digital Content Manager

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	April 29, 2011
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 29, 2011
Last Ship Date License	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 29, 2011

HW = Hardware OS SW = Operating System Software App. SW = Application Software

This is a product part number change only, effective immediately. Customers will experience no change in functionality, service, or lead time when using the new product IDs. The new product IDs are designed to simplify the ordering process. Customers are encouraged to migrate immediately to the Cisco D9900/D9901 Digital Content Manager configurable through the Cisco Dynamic Configuration Tool (<https://apps.cisco.com/qtc/config/jsp/configureHome.jsp>). The Cisco Dynamic Configuration Tool allows online configuration of the Cisco D9900/D9901 Digital Content Manager (DCM-1RU and DCM-2RU) as well as DCM License Upgrade Kits (DCM-LIC-UPGR). Spare parts are available under Cisco DCM Series in the Pricing Tool. Non-migrated Scientific Atlanta customers, still ordering in SAP, are not affected by this product part number change.

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
401134400086	D9900/D9901 MP2 Transrating Lic (86/Lic)	LDCM-SD-MP2TR	D9900/D9901 MP2 SD Transrating Lic (1/SD, req. Co-Pro)	-
401134400294	D9900/D9901 MP2 Transrating Lic (294/Lic)	LDCM-SD-MP2TR	D9900/D9901 MP2 SD Transrating Lic (1/SD, req. Co-Pro)	-
401134600043	D9900/D9901 MP2 Splicing Lic (43/Lic)	LDCM-MP2DPI	D9900/D9901 MP2 DPI Lic (1/SD,2/HD, req. TR; req. Co-Pro)	-
401373800056	D9900/D9901 BU MP2 Transrating Lic (56/Lic)	LDCM-SD-MP2TR	D9900/D9901 MP2 SD Transrating Lic (1/SD, req. Co-Pro)	-
401373900028	D9900/D9901 BU MP2 Splicing Lic (28/Lic)	LDCM-SD-MP2TR	D9900/D9901 MP2 SD Transrating Lic (1/SD, req. Co-Pro)	-
403023400025	D9900/D9901 MPEG2 to AVC HD Xcdr (Reqs Xcdr) (25/Lic)	LDCM-MP24HDTC	D9900/D9901 MP2->AVC HD Transc Lic (1/prg, req. Transc)	-
403023500025	D9900/D9901 BU MPEG2 to AVC HD Xcdr Lic (Reqs Xcdr) (25/Lic)	BDCM-MP24HDTC	D9900/D9901 BU MP2->AVC HD Lic (1/prg, req. Transc)	-
403926100020	D9900/D9901 DCM DRD Descrambling Lic. 20 CI Slot (req DRD)	LDCM-CI-1	D9900/D9901 DCM DRD Descrambling Lic. 1 CI Slot (req DRD)	-
403926300020	D9900/D9901 DCM DRD Satellite Reception Lic. 20 RF (req DRD)	LDCM-SAT-1	D9900/D9901 DCM DRD Satellite Reception Lic. 1 RF (req DRD)	-

Product Migration Options

This is a product part number change only. Customers will experience no change in functionality when using the new product IDs. The new product IDs are designed to simplify the ordering process.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:
http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)