



End-of-Sale and End-of-Life Announcement for the Cisco Secure Access Control Server 3.3 for Windows

Cisco Systems® announces the end-of-sale and end-of life dates for the Cisco® Secure Access Control Server 3.3 for Windows. The last day to order the affected product is August 29, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until August 28, 2009. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the Cisco Secure ACS 4.0 for Windows. More information about the replacement product can be found at: <http://www.cisco.com/go/acs>.

Table 1. End-of-Life Milestones and Dates for the Cisco Secure Access Control Server 3.3 for Windows.

Milestone	Definition	Date
End-of-life announcement date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	February 28, 2006
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	August 29, 2006
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	November 27, 2006
End of software maintenance releases date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	August 29, 2007
End of new service attachment date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	August 29, 2007
End of service contract renewal date	The last date to extend or renew a service contract for the product.	November 24, 2008
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	August 28, 2009

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
CSACS-3.3-WIN-K9	Cisco Secure ACS 3.3 for Windows	CSACS-4.0-WIN-K9	Cisco Secure ACS 4.0 for Windows
CSACS-3.3-WINUP-K9	Upgrade to CSACS 3.3 for Windows from 1.x 2.x and CS Unix	CSACS-4.0-WINUP-K9	Upgrade to CSACS 4.0 for Windows from 1.x 2.x 3.X and CS Unix
CSACS-WNAPR05MR-K9	Minor Release update for CSACS 3.3.3-Apr 05	CSACS-4.0-WIN-K9	Cisco Secure ACS 4.0 for Windows
CSACS-WNAPR05SR-K9	Service use Only; Minor Rel for CSACS 3.3.3-Apr 05	CSACS-4.0-WIN-K9	Cisco Secure ACS 4.0 for Windows

CSACS-WNNOV04SR-K9	Service use Only; Minor Rel for CSACS 3.3.2	CSACS-4.0-WIN-K9	Cisco Secure ACS 4.0 for Windows
--------------------	--	------------------	-------------------------------------

PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco Secure Access Control Server is the Cisco Secure ACS 4.0 for Windows. More Information about this product can be found at: www.cisco.com/go/acs.

FOR MORE INFORMATION

For more information about the Cisco Secure Access Control Server, visit http://www.cisco.com/en/US/products/sw/secursw/ps2086/prod_eol_notices_list.html or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:
http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to:
<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco.com Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic
Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy
Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

C51-337498-00 02/06